

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	1	0	1	0	1	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	3		3		3				
2	NLG	144	988		1		1		1			
3	MDK	107	933	2		2		2				
4	SDPT				6		6		6			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	5	7	5	7	5	7	0	0	
	Grand Total	1082	6468	5	8	5	8	5	8	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 28.03.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Amarchintha	Atmakur	33KV	Wanaparthu	01.40	03.05	01.25	EL	Jumper cut at 132KV Amarchintha	Atmakur	-
2		Wanaparthu	Buddaram	33KV	Wanaparthu	16.38	18.30	01.52	EL	33KV Conductor snapped at Tadiparthi	Buddaram	-
3		Alampur	Shanthinagar -1	33KV	Gadwal	05.16	10.58	05.42	EL	Tree fallen on the line	Shanthinagar -1	-
1	MDK	Gummadidala	GPSS-I	33KV	Patancheru	04.10	05.55	01.45		B/D due to Pin binding failed	GPSS-I	-
2		Gummadidala	Gummadidala	33KV	Patancheru	20.00	21.30	01.30		B/D due to Conductor snapped	Gummadidala	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 28.03.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Akupamula	Akupamula	11KV	Huzurnagar	05.30	07.30	02.00	EL	11 KV LINE SNAPPED	-
1	SDPT	Thimmapur	Thimmapur	11KV	Siddipet	18.30	19.10	00.40		11kv LINE CUT	-
2		Thimmapur	Thimmapur	11KV	Siddipet	19.37	20.28	00.51		11kv LINE CUT	-
3		Dubbak	Chellapur	11KV	Siddipet	07.25	08.35	01.10		BD DISC FAIL	-
4		MARKOOK	MARKOOK AGL	11KV	Gajwel	07:30	08:05	00.35		11KV LINE CUT	-
5		GOWRARAM	PATHUR	11KV	Gajwel	08.10	11.10	03.00		BD DISC FAIL	-
6		MULUGU	NAGIREDDYPALLI	11KV	Gajwel	13.35	14.50	01.15		11kv LINE CUT	-
1	HYD S	Gunj	Gunj	11KV	VIII	22.39	23.50	01.11	All Indication	Lorry dashed to HT Pole & Jumpers cut at Race course wall	