

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		3		3		3			
7	RR(E)	168	403		7		7		7			
8	Hyd	194	1044	1	6	1	6	1	6			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>1</b>	<b>16</b>	<b>1</b>	<b>16</b>	<b>1</b>	<b>16</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	3	6	3	6	3	6			
2	NLG	144	988	1	11	1	11	1	11			
3	MDK	107	933									
4	SDPT			1	6	1	6	1	6			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>5</b>	<b>23</b>	<b>5</b>	<b>23</b>	<b>5</b>	<b>23</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>6</b>	<b>39</b>	<b>6</b>	<b>39</b>	<b>6</b>	<b>39</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 22.08.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Makthal	Narwa	33KV	Narayanapet	05.40	09.50	04.10	O/L	Tree Branch Fallen on the line at Rudrasamudram X Road	Narwa	-
2		Wanaparthi	Kodair	33KV	Wanaparthi	11.20	12.10	00.50	E/L&O/L	Due to LA Blast	Kodair	-
3		Gadwal	Maldakal	33KV	Gadwal	00.45	10.50	10.05	E/L	Insulator Flash Over and Replacement	Maldakal	-
1	NLG	Sh Gowraam	Nakrekal	33KV	Nalgonda	10.05	17.18	07.13		Insulator Failure	Nakrekal	-
1	SDP	Husnabad	Katkur	33KV	Husnabad	12.30	15.35	03.05		BD Pin Insulator Fail	Katkur	-
1	HYD N	132KV Madhapur	SS-1	33KV	Kalyan Ngr	02.33	07.29	04.56	All Indication	VCB blasted in Dell Company	SS-1	-

TSSPDCL - LMRC / Corporate office

Date: 22.08.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Karkonda	Khanapur	11KV	Jadcherla	10.10	14.48	04.38		11Kv jumper Cut Near Chama Gadda Tanda Side	-
2		Konded	Konded	11KV	Jadcherla	02.30	11.45	09.15		11Kv Disc Failure Near Konded( V)	-
3		Janampet	24Hrs	11KV	Jadcherla	00.25	07.10	06.45		Tree Fallen On The 11kv line Near Janampet ( V)	-
4		Janampet	Moosapet	11KV	Jadcherla	00.25	07.30	07.05		11KV Insulator Failure Near Moosapet (V)	-
5		Ponnakal	Rachala	11KV	Jadcherla	09.15	12.50	03.35		11KV line Cut Near GBR Bavi Side	-
6		Marikal	Chakalpally	11KV	Jadcherla	02.40	09.40	07.00		11KV Insulator Failure Near Chakalpally( V)	-
1	NLG	Palem	Palem Feeder	11KV	Nalgonda	04.00	11.00	07.00	EL	11KV Line Jumper Cut	-
2		Eduloor	G.B.Gudem	11KV	Nalgonda	07.30	12.30	05.00	EL	AB switch Problem	-
3		Eduloor	G.B.Gudem	11KV	Nalgonda	13.30	15.00	01.30	EL	AB switch Problem	-
4		Eduloor	G.B.Gudem	11KV	Nalgonda	16.00	17.00	01.00	EL	AB switch Problem	-
5		B.Vellemala	B.Vellemala	11KV	Nalgonda	08.10	10.10	02.00	EL	11KV Line Jumper Cut	-
6		B.Chandupatla	V.K Pahad	11KV	Suryapet	14.25	16.20	01.55	E/L	Tee branch fallen on the line	-
7		Dirsincherla	Narasayagudem	11KV	Huzurnagar	06.00	08.30	02.30	EL	Due to line cutted	-
8		Chanupally	Tripuravaram	11KV	Huzurnagar	06.00	09.00	03.00	EL	Due to 11Kv disk failure	-
9		Nadigudem	Ratnavaram	11KV	Huzurnagar	15.20	17.00	01.40	EL	Due to 11Kv line snapped	-
10		Chada	Katepally	11KV	Bhongir	05.00	08.20	03.20	EL	11kv Line snapped near Motakondur Village	-
11		Rajapet	Renikunta AGL	11KV	Bhongir	10.30	12.00	01.30	EL	11KV Insulator Failed near Begampet Village	-
1	SDP	Nagapuri	Pothireddypally	11KV	Husnabad	10.15	10.50	00.35		Disc Failed	-
2		Dhulimitta	Arjunpatla	11KV	Husnabad	07.40	10.50	03.10		Line Snapped	-
3		Husnabad	Madatha	11KV	Husnabad	00.02	07.10	07.08		BD Rectified Automatic	-
4		Husnabad	Husnabad T 2	11KV	Husnabad	13.20	14.05	00.45		Disc Failed	-
5		Koheda	Theegalakuntapally	11KV	Husnabad	14.30	15.10	00.40		Line Snapped	-
6		Koheda	Kureela	11KV	Husnabad	15.30	15.50	00.20		BD Ht/LT lines twisted	-
1	RR N	Laxmapur	IDA Laxmapur	11KV	Medchal	18.14	19.35	01.21	BD	11KV Pin Insulator Failed at Ricemill backside,RR Garden Main Road	-
2		Nuthankal	Bharathi	11KV	Medchal	17.55	19.05	01.10	BD	Tree fallen on the 11KV Line at Pochamma Temple,Nuthankal	-
3		Ravalkole	Cheruvukatta	11KV	Medchal	16.15	16.55	00.40	BD	Tree fallen on the 11KV Line at Foultry Farm	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR E	Uppal	Uppal	11KV	Habsiguda	15.55	16.50	00.55		11KV Pin Insulator failed near Padma Laxamma DTR at Laxma Reddy Colony	-
2		Nacharam	Times Of India	11KV	Habsiguda	16.10	17.25	01.15		11KV Pin Insulator failed near Kalpana Chemical Opposite	-
3		Kushaiguda	Neredmet	11KV	Sainikpuri	10.10	11.30	01.20		11Kv cable cut at Pariwar Hotel back side (LM Srinivas)	-
4		AS Rao Nagar	Gandhi Nagar	11KV	Sainikpuri	16.14	17.09	00.55		11Kv Insulator failed at MJ Colony Road No.3 1/2 bit charged ok due to line AB Switch Open (LM Anjaneyulu)	-
5		Moula-Ali	Malkajgiri	11KV	Sainikpuri	16.00	17.38	01.38		11Kv line touched to 11.1 cement pole at Hanuman Nagar near Pochamma Temple (L.Insp Venkateshwarulu)	-
6		Vinayak Nagar	Neredmet Diet	11KV	Sainikpuri	19.02	19.57	00.55		11Kv Disk failed at SSV Appartment LB Nagar (AE/OP/L.Insp MS Rao)	-
7		Narapally	Prathap Singaram	11KV	Keesara	16.26	17.26	01.00		11KV Disc failed at Maktha Village	-
1	HYD N	New Bowenpally	Raju Colony	11KV	VI	15.40	18.20	02.40	EL,OL-Bph	Pin Insulator flash over at Gaddi Basti	-
2		Marredpally	Lalitha Nagar	11KV	C-VI	15.55	18.40	02.45	OL-Bph	Jumper cut on Line AB Switch at G.S.Super Market & Disc Insulator flash over at Railway Colony DTR	Arranged B/F on 11KV Contonment feeder
3		Gunrock	Tirumalagiri	11KV	C-VI	17.22	20.10	02.48	All Indication	Pin Insulator flash over at RTO Office, Jumper cut at Kanta & Tree branches fallen on lines at LIC Building	At 19:05 Hrs partial fdr B/F arranged on 11KV Srinagar Colony fdr
1	HYD S	Kulsumpura	R.K.Pet	11KV	IX	00.25	01.32	01.07	EL,OL	Cable fault	Arranged B/F on 11KV Dhoolpet OH fdr
2		Ch' Baradari	Doodh Bowli	11KV	III	01.29	02.55	01.26	EL,OL	Cable fault at Imlika Jad	Arranged B/F on 11KV Rama Talkies feeder
1	HYD C	Bathkammakunta	Ahobilmutt	11KV	II	17.58	19.24	01.26	OL-Bph	Tree branches fallen on lines at Opp: Hotel Management	-