

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044									
	Total	606	3055	0	0	0	0	0	0	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988	1	6	1	6	1	6			
3	MDK	107	933		1		1		1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	7	2	7	2	7	0	0	
	Grand Total	1082	6468	2	7	2	7	2	7	0	0	

TSSPDCL - LMRC / Corporate office

Date: 24.12.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthi	Peddmandadi	33KV	Wanaparthi	17.27	18.06	00.39	O/L	Due to Line Problem	Peddmandadi	Alternate supply arranged form 33KV Veltoor SS at 18:06Hrs.
1	NLG	Kanagal	Thurkapally	33KV	Nalgonda	10.15	14.20	04.05	EL	Lighting Arrested Failed	Thurkapally	-

TSSPDCL - LMRC / Corporate office

Date: 24.12.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Kattangur	Dugenvelly	11KV	Nalgonda	08.10	11.00	02.50	EL	11KV Jumper cut	-
2		Shaligouraram	Shaligouraram	11KV	Nalgonda	06.30	09.20	02.50	EL	11KV Jumper cut	-
3		Annaram	Kothagudem	11KV	Suryapet	08.30	11.40	03.10	EL	Insulator failed	-
4		Gondriyala	Chimiryala	11KV	Huzurnagar	06.06	09.00	02.54	OL	Due to 11Kv insulator failure	-
5		Mattampally	Lift	11KV	Huzurnagar	14.10	15.40	01.30	EL	Due to 11Kv line cutted	-
6		Chamapur	Chamapur	11KV	Bhongiri	09.00	10.10	01.10	EL	11KV Insulator Failed at SS-4 Near Chamapur Village.	-
1	MDK	Bollaram-I	Kythan	11KV	Patancheru	06.00	10.00	04.00		B/D Due to Conductor snapped	-