

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044		2		2		2			
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		3		5		5			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	3	0	5	0	5	0	0	
	Grand Total	1082	6468	0	6	0	8	0	8	0	0	

TSSPDCL - LMRC / Corporate office

Date: 26.12.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	N.B.Gudem	Redlakunta	11KV	Huzurnagar	01.10	04.15	03.05	EL	Due to 11Kv line cutted	-
2		Ishkilla	Uthatoor	11KV	Choutuppal	03.20	09.50	06.30	EL	11 kv Insulator Failed Near Uthatoor Village.	-
3		Choutuppal	Jublakpally	11KV	Choutuppal	05.00	10.00	05.00	EL	11 kv Insulator Failed Near Lakkaram Village.	-
1	RR N	Shameerpet	Devarayamjal	11KV	Medchal	16.22	17.05	00.43		Bird fallen on the 11Kv Line at Lingala bavi, Thumkunta	-
1	HYD N	I.D.P.L	Bala Nagar	11KV	Bowenpally	08.20	09.30	01.10	EL,OL-Rph	Foreign material fallen on lines at Plot No.B9	-
1	HYD C	Bathkammakunta	Saibaba Temple	11KV	Azamabad	14.36	15.52	01.16	EL	No Visible Fault	Arranged B/F on 11KV Ahobilmutt fdr