

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044	1	3	1	3	1	3			
	Total	606	3055	1	6	1	6	1	6	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2	2	2	2	2	2			
2	NLG	144	988	1	7	1	7	1	7			
3	MDK	107	933	1	1	1	1	1	1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	4	10	4	10	4	10	0	0	
	Grand Total	1082	6468	5	16	5	16	5	16	0	0	

TSSPDCL - LMRC / Corporate office

Date: 17.07.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Kalwakurthy	Rachoor	33kv	Nagarkurnool	02.05	07.50	05.45	E/L	Pin Insulator Damaged at Kalwakurthy	Rachoor	-
2		Kodangal	Dudyal	33kv	Vikarabad	23.10	23.30	00.20	E/L	Due to Wind	Dudyal	-
1	NLG	Bhongiri	M.R.Gudam	33kv	Bhongiri	17.38	20.25	02.47		Disk Failed	M.R.Gudam	-
1	MDK	Zaheerabad	Machanoor	33kv	Zaheerabad	14.35	18.35	04.00		BD due to Conductor snapped & alternate supply arranged from 33KV Jharasangem feeder	Machanoor	-
1	HYD N	132KV Imlibun	Durga Nagar (Idle)	33kv	Asmangadh	08.55	11.53	02.58	EL,OL-Rph	Jumper cut at LOC.No.10	Durga Nagar (Idle)	-

TSSPDCL - LMRC / Corporate office

Date: 17.07.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Mothiganapur	Gangadarpally	11kv	Jadcherla	03.00	10.00	07.00		11KV Disk fail near SS	-
2		Gundlapotlapally	B.B.Nagar	11kv	Jadcherla	04.00	11.00	07.00		Tree Fallen the line near Mallepally	-
1	NLG	Nuthankal	Chilapuntla	11kv	Suryapet	07.20	09.30	02.10	E/L	Conductor Snapped	-
2		Gaddipaly	Ponugodu	11kv	Huzurnagar	07.15	10.25	03.10	EL	Due to tree branch fall on 11kv line	-
3		Garidepally	Kalmalchervu	11kv	Huzurnagar	07.05	09.30	02.25	EL	Due to 11Kv Jumper cutted	-
4		Mattapally	Sulthanpuram	11kv	Huzurnagar	06.20	09.20	03.00	EL	Due to 11Kv Jumper cutted	-
5		Dirsincherla	Somaram	11kv	Huzurnagar	13.00	15.00	02.00	EL	Due to 11Kv line snapped	-
6		Eduloor	Parada	11kv	Nalgonda	15.50	19.00	03.10	EL	Jumper Cut	-
7		Eduloor	Munukuntla	11kv	Nalgonda	17.15	19.00	01.45	EL	Jumper Cut	-
1	MDK	Bollaram - II	Vasavidatta	11kv	Patancheru	17.20	18.50	01.30		BD due to Insulator failed	-
1	RR N	Kompally	Kompally	11kv	Medchal	08.30	09.30	01.00	BD	11KV Cable Failed at Lift Complex, Grampanchayath Opposite	-
2		UMCC	HAL Colony	11kv	Medchal	16.15	16.50	00.35	BD	11KV Line Melted at Ushodaya Colony	-
1	RR E	P&T Colony	Chengicherla	11kv	Keesara	06.00	08.00	02.00		11KV Disc failed near Chengicherla Park	-
1	HYD S	Miralam	Madina Masjid	11kv	Charminar	16.50	18.05	01.15	EL	Cable Fault	Arranged B/F on 11KV Hasan Nagar feeder
1	HYD N	H.M.T	A.O.L.	11kv	Bowenpally	11.55	13.10	01.15	EL	AB Cable fault at Sri Sai Garden	-----
2		I.D.P.L	Shivalayam	11kv	Bowenpally	18.30	19.45	01.15	EL,OL-Rph	Cable fault at Railway Bridge	-----