

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044	1	1	1	1	1	1			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>1</b>	<b>2</b>	<b>1</b>	<b>2</b>	<b>1</b>	<b>2</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988		3		3		3			
3	MDK	107	933									
4	SDPT				1		1		1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>1</b>	<b>4</b>	<b>1</b>	<b>4</b>	<b>1</b>	<b>4</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>2</b>	<b>6</b>	<b>2</b>	<b>6</b>	<b>2</b>	<b>6</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 11.11.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Nagarkurnool	Peddakothapally	33kv	Nagarkurnool	13.53	17.26	03.33	EL	Tree follen on the line at Peddakothapally Town	Peddakothapally	-
1	HYD N	132KV Jubilee Hills	MLA Colony	33kv	Jubilee Hills	10.25	10.38	00.13	Rph with heavy dip	End Kit failed at Road No.45 Petrol Pump & Bala Krishna's House	MLA Colony	Loads transferred onto 132KV J' Hills SS via 33KV Asif Nagar Ckt-1

## TSSPDCL - LMRC / Corporate office

Date: 11.11.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Thungathurthy	Pasnoor	11kv	Suryapet	11.30	14.30	03.00	E/L	11Kv Insulator failed	-
2		Akupamula	Kodandarampuram	11kv	Huzurnagar	14.00	15.30	01.30	E/L	11Kv Line Snapped	-
3		Mothkur	Anajipur	11kv	Bhongir	09.30	12.00	02.30	EL	11kv Line snapped near Dacharam (V)	-
1	SDPT	Husnabad	Husnabad Town-1	11kv	Husnabad	16.45	17.25	00.40		Bird fallen on line, same rectified	-
1	RR N	Jeedimetla SS V	Rudralaya	11kv	Jeedimetla	12.10	14.05	01.55	EL/OL	Lorry dash to the 4 No of poles opp Rudralaya Company	-
1	HYD S	Falaknuma	Fathima Nagar	11kv	Charminar	11.18	12.44	01.26	OL	Jumper cut & B/o Lugs at Urdu School	