

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044	1	4	1	4	1	4			
	Total	606	3055	1	7	1	7	1	7	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		2				
2	NLG	144	988		3		3		3			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	3	2	3	2	3	0	0	
	Grand Total	1082	6468	3	10	3	10	3	10	0	0	

TSSPDCL - LMRC / Corporate office

Date: 01.10.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Balanagar	Nava Durga	33KV	Jadcherla	15.22	18.12	02.50	EL	Pin insulator failed and replaced near Balanagar BSNL Office	Nava Durga	-
2		Amangal	Kadthal	33KV	Shadnagar	17.05	17.36	00.31	EL	Not Rectified Alternate Supply Given	Kadthal	Alternate Supply Arranged from 33KV Mudwin feeder at 17:36Hrs
1	HYD N	132KV Erragadda	Srinagar Colony	33KV	Kalyan Ngr	17.41	17.46	00.05	OL-Yph	Cable End Kit failed near 33KV Srinagar Colony SS	Srinagar Colony	Loads transferred onto 132KV Erragadda SS via 33KV Yellareddyguda SS

TSSPDCL - LMRC / Corporate office

Date: 01.10.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Reddygudem	Reddygudem	11KV	Suryapet	03.30	07.40	04.10	E/L	Conductor snapped	-
2		Kistapuram	Thammaram	11KV	Huzurnagar	15.55	17.00	01.05	EL	Due to 11Kv line snapped	-
3		Sirikonda	Namavaram	11KV	Huzurnagar	12.00	15.00	03.00	EL	Due to 11Kv line cutted	-
1	RR N	Devarayamjal	Kottapet	11KV	Medchal	10.40	11.10	00.30	BD	Tree Branch fallen on the 11KV Line at Metro Godown	-
2		Kolthur	Kolthur	11KV	Medchal	08.30	10.40	02.10	BD	11KV Pin Insulator failed at Naaluka Mallesh Bhavi	-
1	RR E	Singaur	RGK	11KV	Keesara	19.22	20.40	01.18		11KV Pin Insulator failed at NTPC Backside	-
1	HYD N	Hakimpet	Risala Bazar	11KV	C-VI	09.45	10.50	01.05	All Indciation	No Visible Fault	-
2		Hakimpet	Bollaram PS	11KV	C-VI	09.55	11.15	01.20	EL	No Visible Fault	-
1	HYD S	Kandikal Gate	Patel Nagar	11KV	III	19.50	20.56	01.06	EL	Cable fault	Arranged B/F on 11KV Gowlipura fdr
1	HYD C	Z.P Office	Banjara Avenue	11KV	I	05.24	06.58	01.34	EL	Tree branches fallen on lines at Saraswathi Vidya Mandir	-