

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550	1	4	1	4	1	4			
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	1	6	1	6	1	6	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	4		2		2				2 No.s Still
2	NLG	144	988		4		4		4			
3	MDK	107	933	1		1		1				
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	5	6	3	6	3	6	0	0	
	Grand Total	1082	6468	6	12	4	12	4	12	0	0	

TSSPDCL - LMRC / Corporate office

Date: 02.10.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Mahabubnagar	SVS Eidra	33KV	Mahabubnagar	22.46	23.45	00.59	E/L&O/L	Not Rectified Alternate Supply Taken to 33KV Jadcherla Feeder	SVS Eidra	-
2		Palkonda	Bhoothpur	33KV	Mahabubnagar	19.33	23.05	03.32	E/L&O/L	Insulator Failed at Bhoothpur Village	Bhoothpur	-
3		Palkonda	Janampet	33KV	Mahabubnagar	19.33			E/L&O/L		Janampet	-
4		Sri Rangapur	Kondurgu	33KV	Shadnagar	23.35			E/L		Kondurgu	-
1	MDK	Gummadidala	Gummadidala	33KV	Patancheru	13.00	16.05	03.05	BD due to Tree branches fallen on line	Gummadidala		-
1	RR N	132KV Medchal	33KV Medchal -I	33KV	Medchal	01.30	04.43	03.13		33KV Disc failed at near by SS	33KV Medchal -I	-

TSSPDCL - LMRC / Corporate office

Date: 02.10.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Ravulapally	Ravulapally	11KV	Suryapet	04.30	07.20	02.50	E/L	11Kv Insulator flashover	-
2		Choputuppal	Lingo jigudem	11KV	Choputuppal	06.00	09.50	03.50	E/L	11kv Insulator Failed at Divis Company Near Choutuppal (V)	-
3		Choputuppal IPDS	Dhamara	11KV	Choputuppal	08.00	13.24	05.24	E/L	11kv Insulator Failed Near Dhamara (V)	-
4		Kopple	Kopple	11KV	Nalgonda	10.05	14.20	04.15	E/L	11 KV Jumper Cut	-
1	SDP	Koheda	Theegalakuntapally	11KV	Siddipet	08.30	11.15	02.45		BD, Conductor snapped	-
2		Gurjakunta	Vechareni	11KV	Siddipet	07.00	13.00	06.00		BD, Due to rain	-
1	RR S	ESCI	Nanakramguda	11KV	Gachibowli	15.36	17.18	01.42		11KV UG Cable Damaged at Divya Sree	-
1	RR N	UMCC	RM Nagar	11KV	Medchal	00.45	01.20	00.35		11KV Brass Patti cut and replaced at Umadevi Nagar	-
2		UMCC	Crusher	11KV	Medchal	17.20	17.57	00.37		Line AB Switch opened at Devendhar nagar(11KV Line melted)	-
3		Shameerpet	33KV Leo Meridian	11KV	Medchal	10.20	15.39	05.19		33KV Cable endkit failed at Upparapally Village	-
4		Devarayamjal	Kottapet	11KV	Medchal	15.20	16.45	01.25		11KV Disc failed at Metro Godam	-
1	HYD N	LV Prasad Marg	LV Prasad Film Lab	11KV	X	05.10	08.14	03.04	All Indication	Faulty 11KV Gymkhana Club feeder Bus Breaker at SS	-