

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	2	2	2	2	2	2			
7	RR(E)	168	403		7		7		7			
8	Hyd	194	1044		11		11		11			
	Total	606	3055	2	20	2	20	2	20	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	3	1							
2	NLG	144	988	1	5							
3	MDK	107	933	1	3							
4	SDPT			1	1							
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	6	10	0	0	0	0	0	0	
	Grand Total	1082	6468	8	30	2	20	2	20	0	0	

TSSPDCL - LMRC / Corporate office

Date: 05.10.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthy	Revally	33kv	Wanaparthy	16.40	16.50	00.10	O/L	Line Twisted at 220KV Wanaparthy Yard	Revally	-
2		Wanaparthy	Chinnamaroor	33kv	Wanaparthy	16.40	16.50	00.10	E/L	Line Twisted at 220KV Wanaparthy Yard	Chinnamaroor	-
3		Shadnagar	Mamidi Pally	33kv	Shadnagar	14.10	16.55	02.45	E/L	CB to CT Y Phase Limb clamp & Jumper Replacement at 220KVSS	Mamidi Pally	-
1	NLG	Mattampally	Grey Gold	33kv	Huzurnagar	19.44	21.24	01.40	EL	B/D due to CT Flash	Grey Gold	-
1	MDK	Bollaram	Arobindow III & XII	33kv	Patancheru	14.00	16.00	02.00		BD due to Tree branches fallen on line	Arobindow III & XII	-
1	SDPT	Habsipur	Khajipur	33kv	Siddipet	15.10	16.30	01.20		BD, Falt on Back Feeding Poing	Khajipur	-
1	RR N	132KV Malkaram	33KV Shameerpet	33kv	Medchal	07.08	08.33	01.25		Plastic Cover Fallen on the 33KV Line at near by BITS SS	33KV Shameerpet	-
2		132KV Malkaram	33KV Ratnalayam	33kv	Medchal	07.08	08.33	01.25		Plastic Cover Fallen on the 33KV Line at near by BITS SS	33KV Ratnalayam	-

TSSPDCL - LMRC / Corporate office

Date: 05.10.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kodgal	Kodgal	11KV	Jadcherla	08.10	12.10	04.00		DTR Failed Near Laxminayak Thanda	-
1		Eduloor	G.B.Gudem	11KV	Nalgonda	09.30	10.30	01.00	E/L	11KV jumper cut	-
2		Penpahad	Annaram	11KV	Suryapet	15.15	17.00	01.45	E/L	Tee branch fallen on the line	-
3		Gaddipally	Gaddipally	11KV	Huzurnagar	04.30	06.30	02.00	EL	11 KV LINE SNAPPED	-
4	NLG	Bollepally	Bollepally	11KV	Bhongir	09.00	10.30	01.30	OL	HT/HT & 1 NO. 11 kv Pole Dammaged Near Bollepally Village.	-
5		Juloor	Pilaipally	11KV	Choutuppal	06.00	09.15	03.15	EL	11 kv Disc Failed & 1 no LT Pole Dammaged Near Jagathpally Village	-
1	MDK	Bollaram - II	Rupa	11KV	Patancheru	16.50	18.20	01.30		BD due to Disk failed	-
2		Anrich Bollaram	Town-II	11KV	Patancheru	14.00	15.22	01.22		BD due to Jumper cut	-
3		Pati	Pati	11KV	Patancheru	09.10	10.40	01.30		BD due to Jumper cut	-
6	SDPT	Guruvannapet	Guruvannapet	11KV	SDPT	22.00	23.30	01.30		B/D due to line problem	-
1		Kompally	NCL	11KV	Medchal	10.01	11.25	01.24		11KV Line AB Switch Opened at Croma	-
2	RR N	Ravalkole	IDA Ganapathi	11KV	Medchal	17.00	18.00	01.00		Tree fallen on the 11KV Line at Sneha farm,Rajabollaram Thanda	-
1		Mallapur-2	Narsimha Nagar	11KV	Habsiguda	02.04	02.40	00.36		11KV Disc failed near Indian Bank at Mallapur	-
2		IDA Uppal	Jersey	11KV	Habsiguda	15.33	16.10	00.37		Tree branches fallen on 11KV line near Rajeev Industry at IDA Uppal	-
3		Malkajiri	Uttam Nagar	11KV	Sainikpuri	16.08	16.54	00.46		Post of Insulator failed at Street No 4 Dayanand Nagar (AE)	-
4	RR E	Kushaiguda	Neredmet	11KV	Sainikpuri	15.10	16.20	01.10		11KV line AB Switch opened at Patanjali Store line patrolling done no fault found (LM Srinu)	-
5		Peerzathiguda	Peerzathiguda	11KV	Keesara	10.25	10.55	00.30		11KV Pin Insulator failed at Narsimha Reddy Colony	-
6		Aushapur	Bokkenguda	11KV	Keesara	08.00	10.30	02.30		11KV Line twisted at Mandakini Venture	-
7		Aushapur	Aushapur	11KV	Keesara	16.10	17.30	01.20		11KV Pin Insulator failed at Jamulapeta Road	-
1		Miralam	Madina Masjid	11KV	III	14.40	16.25	01.45	All Indication	Cable fault	Arranged B/F on 11KV Hasan Nagar feeder
2	HYD S	Malakpet	Municipal Colony	11KV	VIII	15.25	17.10	01.45	EL,OL-R&Bph	Tree branches fallen on lines at Hanuman Temple	----
3		Teegalaguda	Housing Board Colony	11KV	VIII	15.54	17.10	01.16	OL-Rph	DTR End Kit fault at Housing Board Colony	----
1		Amberpet	Zindatilasmath	11KV	II	15.30	16.55	01.25	EL	Pin Insulator flash over at Nava Bharath PT	----
2		Golnaka	Moulana Azad Nagar	11KV	II	15.34	18.20	02.46	EL,OL	faulty loads of 11KV Tourist Hotel feeder	16:57 Hrs Partial feeder Charged
3		Amberpet	Sanjeevaiah Nagar	11KV	II	15.36	17.30	01.54	EL	Tree branches fallen on lines at D.B.R Apartment	----
4		Vittalwadi	Y.M.C.A	11KV	II	15.46	17.35	01.49	EL,OL-Bph	No Visible fault (due to Rain)	----
5		Bathakamma Kunta	Shivam	11KV	II	15.32	18.11	02.39	EL	Disc Insulator flash over at Water Works	----
6	HYD C	I.T.I Mallepally	Anjuman	11KV	VII	22.29	01.28	02.59	EL,OL-Bph	No Visible fault (due to Rain)	23:28 Hrs partial fdr (46/77) charged, opened AB Switch City Function Hall
7		Golconda	Narayanamma College	11KV	VII	23.20	00.30	01.10	EL,OL-Bph	O/G AB Switch Insulator flash over at SS	----
8		Langer House	Maruthi Nagar	11KV	VII	23.10	00.50	01.40	EL,OL-Bph	Disc Insulator flash over at Jyothi Nagar	----