

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	2	1	2	1	2	1			
7	RR(E)	168	403									
8	Hyd	194	1044	1	2	1	2	1	2			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>3</b>	<b>3</b>	<b>3</b>	<b>3</b>	<b>3</b>	<b>3</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		9		9		9			
3	MDK	107	933	2		2		2				
4	SDPT				1		1		1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>2</b>	<b>10</b>	<b>2</b>	<b>10</b>	<b>2</b>	<b>10</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>5</b>	<b>13</b>	<b>5</b>	<b>13</b>	<b>5</b>	<b>13</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 05.09.19

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Gummadidala	GPSS-1	33KV	Sangareddy	8:53	10:55	2:02		Insulator failed	GPSS-1	No
2		Pashamailaram	BPL	33KV	Sangareddy	11.05	12.15	01.10		Jumper cut	BPL	No
1	RR N	132KV Malkaram	33KV Shameerpet	33KV	Medchal	7:06	10:45	3:39		33KV Line problem at Bits Compound	33KV Shameerpet	No
2		132KV LGM Pet	33KV LGM Pet	33KV	Medchal	02.58	03.30	00.32		33KV Jumper Cut at Chemo Company	33KV LGM Pet	Backfeeding to 33KV Ratnalayam feeder from 132KV Malkaram
1	HYD N	132KV J' Hills - GCB-1	Jubilee Hills (PTR-1)	33KV	Kalyan Ngr	08.00	08.30	00.30	EL,OL-Bph	Cable End Kit failed at inside 132KV J' Hills SS	Jubilee Hills (PTR-1)	Loads transferred onto GCB-2 PTR-2

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Raghunadapalem	Nakkalagudem	11KV	Huzurnagar	12.40	14.30	01.50	EL	Due 11KV Jumper cut	No
2		Nadigudem	Ramapuram	11KV	Huzurnagar	15.00	16.10	01.10	EL	Due to 11KV Insulator failure	No
3		Thoragal	Ganganaigudem	11KV	Nalgonda	03.00	06.00	03.00	EL	25KV DTR failed	No
4		Pamanagudla	Ismailpally	11KV	Nalgonda	4:00	8:20	4:20	EL	11KV Insulator failed	No
5		B.Ramaram	Jalalpur	11KV	Bhongir	10:30	11:30	1:00	EL	11KV Pin insulator failed near Pedda Parvathapur Village	No
6		Sharajipet	Tangutoor	11KV	Bhongir	10.20	13.15	02.55	EL	11KV Disc failed at Jala Mallareddy Well near Tangutoor Village.	No
7		Peddakandukur	Bahupeta	11KV	Bhongir	06.00	08.43	02.43	EL	11KV Insulator failed near Bahupeta Village.	No
8		Marriguda	Water Grid	11KV	Devarakonda	17.10	19.00	01.50	EL	11KV Insulator failed	No
9		Shivannagudam	R.R.Pally	11KV	Devarakonda	12:15	14:50	2:35	EL	HT/LT	No
1	SDPT	Komuravelli	Kadaverugu	11KV	Husnabad	8:05	9:35	1:30		Due to Heavy gale and wind	No
1	RR N	Town Medchal	NGO's Colony	11KV	Medchal	0:05	1:40	1:35		11KV Disc failed at 4th Pole Structure, Bondalagadda	No
1	HYD N	E.S.I	Bapu Nagar	11KV	IV	11.32	13.07	01.35	EL,OL-Rph	Pin Insulator flash over at Grave Yard	No
2		Allwyn	E.S.I.	11KV	IV	20:18	21:30	1:12	EL	I/C Cable fault at E.S.I.	Arranged B/F on 11KV Bapu Nagar feeder