

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044	1		1		1				
	Total	606	3055	1	1	1	1	1	1	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988		5		5		5			
3	MDK	107	933									
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	7	1	7	1	7	0	0	
	Grand Total	1082	6468	2	8	2	8	2	8	0	0	

TSSPDCL - LMRC / Corporate office

Date: 06.04.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Amangal	Polepally	33KV	Shadnagar	18.30	20.20	01.50	E/L	Pin Binding Failed Near Medigadda(V)	Polepally	-
1	HYD N	132KV Jubilee Hills	Hitech City	33KV	Kalyan Ngr	13.16	19.15	05.59	OL-Rph	Cable damaged by TRANSCO wing near Lemon Tree Hotel	Hitech City	Loads transferred onto 132KV J'Hills SS via 33KV Madhapur fdr

TSSPDCL - LMRC / Corporate office

Date: 06.04.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Thadakamalla	Jai Kisan Lift Feeder	11KV	Miryalaguda	08.00	14.00	06.00	EL	Line Snapped	-
2		Damarcherla	Damarcherla	11KV	Miryalaguda	06.28	08.47	02.19	EL	Insulator Failed	-
3		Thtatipamula	Thtatipamula	11KV	Suryapet	12.10	14.05	01.55	E/L	Conductor snapped	-
4		Gondriyala	Gondriyala 01	11KV	Huzurnagar	12.20	15.10	02.50	EL	Due to 11kv jumper cutted	-
5		Gaddipally	Ponugodu	11KV	Huzurnagar	04.00	07.00	03.00	EL	Due to 11kv Insulator failure	-
1	SDP	Kondapaka (Marpadaga SS)	MEDHINIPUR SS, BOPPAIPALLY FEEDER	11KV	Husnabad	08.50	13.30	04.40		Jumper cut	-
2		Doulthabad	DIPAYAMPALLY FEEDER	11KV	Husnabad	09.36	11.38	02.02		Tree Branches Fallen on line	-
1	RR E	Cherlapally-I	Nagaram	11KV	Sainikpuri	15.00	16.05	01.05		Post Off Insulator failed at Bagavan Colony T/F (Artisan Santhosh Reddy)	-