

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1	1	1	1	1	1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044									
	Total	606	3055	1	2	1	2	1	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	1	1	1	1	1			
2	NLG	144	988		2		2		2			
3	MDK	107	933									
4	SDPT				5		5		5			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	8	1	8	1	8	0	0	
	Grand Total	1082	6468	2	10	2	10	2	10	0	0	

TSSPDCL - LMRC / Corporate office

Date: 16.04.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Marikal	Eklaspur	33kv	Narayanapet	13.55	16.55	03.00	E/L	Breker Trip Coil Burn Out & Conductor Snapped at Rampur Gate	Eklaspur	-
1	RR N	132KV Malkaram	33KV Shameerpet	33kv	Medchal	12.55	14.55	02.00		No visible Fault	33KV Shameerpet	-

TSSPDCL - LMRC / Corporate office

Date: 16.04.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Hemajipur	Hemajipur	11KV	Jadcherla	08.25	12.10	03.45		11KV Wire cut near Thimmareddypally	-
1	NLG	Palakaveedu	Palakeedu agl	11KV	Huzurnagar	04.20	07.20	03.00	OL	Due to 11kv jumper cutted	-
2		Gurraladandi	Ramulugundathanda	11KV	Bhongiri	09.40	11.15	01.35	EL/OL	11kv Insulator Failed near Ramulugundathanda	-
1	SDPT	PREGNAPUR SS	GUNDENNA PALLY AGL	11KV	SDPT	16.00	17.40	01.40		Due to tree branches fallen on line	-
2		WARGAL SS	WARGAL AGL	11KV	SDPT	10.30	11.28	00.58		Due to tree branches fallen on line	-
3		MARPADAGA SS	KHAMMAM PALLY AGL FEEDER (LC.NO:21171)	11KV	SDPT	8:40	9:50	1:10		Due to tree branches fallen on line	-
4		MARPADAGA SS	KHAMMAM PALLY AGL FEEDER (LC.NO:21172)	11KV	SDPT	12:15	16:05	3:50		Due to tree branches fallen on line	-
5		THIMMAREDDY PALLY SS	MATH PALLY FEEDER (LC.NO: 14351)	11KV	SDPT	11:30	12:40	1:10		Due to tree branches fallen on line	-
1	RR N	RGK Suraram	RGK	11KV	Jeedimetla	11.37	12.37	01.00	EL	11KV Insulator failure near 22 block at RGK	-
1	RR E	CRPF	LV	11KV	Keesara	05.05	05.54	00.49		LV Breaker limb fault at SS Yard & B/F from 11KV Dental College feeder & Load normalised at 13:30	-