

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1	1	1	1	1	1			
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	1	2	1	2	1	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		2				
2	NLG	144	988		1		1		1			
3	MDK	107	933									
4	SDPT				18		18		18			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	19	2	19	2	19	0	0	
	Grand Total	1082	6468	3	21	3	21	3	21	0	0	

TSSPDCL - LMRC / Corporate office

Date: 01.04.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthi	Solipur	33KV	Wanaparthi	07.15	08.30	01.15	E/L	Due to Loose Pan	Solipur	-
2		Alampur	Undavelly	33KV	Gadwal	14.46	16.02	01.16	E/L&O/L	Chameleon Fallen on the 33KV Line Near 132KV SS Alampur cut point	Undavelly	-
1	RR N	132KV Medchal	33KV Shantha Biotech	33KV	Medchal	15.01	19.27	04.26	BD	33KV Jumper cut and replaced in SS	33KV Shantha Biotech	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 01.04.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Shanthinagar	Bojjagudem	11KV	Huzurnagar	23.00	01.00	03.00	EL	Due to 11Kv jumper cutted	-
1	SDPT	THIGUL	INDRASTRAL LC No. 6781	11KV	Gajwel	16.12	18.40	02.28		Tree branches fallen on the line	-
2		CHATLAPALLY	ANTHAYAGUDA LC No. 14375	11KV		15.10	17.25	02.15		B/D due to jumper cut	
3		CHATLAPALLY	CHATLAPALLY LC No. 14376	11KV		17.00	19.10	02.10		B/D due to Insulator fail	
4		PREGNAPUR	GUNDANAPALLY LC No. 575	11KV		13.33	17.45	01.12		Tree branches fallen on the line	
5		GANESHPALLY	GANESHPALLY TOWEN LC No. 5498	11KV		12.10	12.55	00.45		B/D due to Insulator fail	
6		THIMAREDDYPALLY	THIMAREDDYPALLY LC No. 28034	11KV		15.30	17.45	02.15		B/D due to rain	
7		DOULTHABAD	DEEPAYAMPALLY LC No. 11481	11KV		16.12	17.34	01.24		B/D due to 100 KV brass cut	
8		DHARMAREDDYPALLY	DHARMAREDDYPALLY LC No. 6342	11KV		13:48	14:52	01:14		B/D due to pole damaged	
9		THIGUL	INDRASTRAL LC No. 6781	11KV		16.12	18.40	02.28		Tree branches fallen on the line	
10		CHATLAPALLY	ANTHAYAGUDA LC No. 14375	11KV		15.10	17.25	02.15		B/D due to jumper cut	
11		CHATLAPALLY	CHATLAPALLY LC No. 14376	11KV		17.00	19.10	02.10		B/D due to Insulator fail	
12		PREGNAPUR	GUNDANAPALLY LC No. 575	11KV		13.33	17.45	01.12		Tree branches fallen on the line	
13		GANESHPALLY	GANESHPALLY TOWEN LC No. 5498	11KV		12.10	12.55	00.45		B/D due to Insulator fail	
14		THIMAREDDYPALLY	THIMAREDDYPALLY LC No. 28034	11KV		15.30	17.45	02.15		B/D due to rain	
15		DOULTHABAD	DEEPAYAMPALLY LC No. 11481	11KV		16.12	17.34	01.24		B/D due to 100 KV brass cut	
16		AKKANAPET	PAKILNAYAK THANDA	11KV		02.10	05.00	02.50		Tree branches fallen on the line	
17		SHANIGARAM	SHANIGARAM TOWN	11KV		09.20	10.20	01.00		Line snapped	
18		Mustyal	veerennapet	11KV		14.10	18.30	04.20		B/D due to Insulator fail	
1	RR N	Aliabad	Jaganguda	11KV	Medchal	14.45	17.15	02.30	BD	11KV Pin Insulator failed and Bird fallen on the 11KV Line at Jaganguda Village	-
1	HYD N	Bowenpally	Pipe Line Road	11KV	Bowenpally	04.35	06.00	01.25	OL-R&Yph	Tree branches fallen on lines & 2No. Jumpers cut at Pipe Line Road	