

TSSPDCL - LMRC / Corporate office

Date: 16.08.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Ghanapur	Lattupally	33KV	Wanaparthu	08.06	11.12	03.06	EL	33KV Pin Insulator Replaced Near Lattupally(V)	Lattupally	No
2		Balanagar	Tommidirekula	33KV	Jadcherla	00.20	07.20	07.00	EL	No Visible Fault was found	Tommidirekula	No
3		Marikal	Koilkonda Water Grid	33KV	Narayanapet	04.30	05.30	01.00	EL	Tree Follen on the line and removed	Koilkonda Water Grid	No
4		leeza	Mittadoddy	33KV	Gadwal	7:26	11:13	3:47	EL	Tree Branch Follen on the line	Mittadoddy	No
1	MDK	Gummadidala	AFA	33KV	Patancheru	5:40	11:30	5:50		Jumper cut near Sundaram Pharma	AFA	No
1	SDPT	Doulthabad	Raipole	33KV	Siddipet	2:40	7:45	5:05		Pole damage	Raipole	No
1	RR N	132KV Medchal	Medchal-I	33KV	Medchal	1:45	3:57	2:12	EL/OL	33KV Jumper cut and replaced at near by Medchal Checkpost	Medchal-I	No
1	HYD C	132KV Asifnaga	SD Hospital	33KV		17.56	18.05	00.09	EL	Cable fault	SD Hospital	Alternate supply arranged. Due to cable fault located between Pillar No.19 and 20, PVNR Express Way.

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	HYD S	Asmangadh	Asmangadh	11KV	VIII	00.32	02.10	01.38	EL	Disc Insulator flash over at Laxman Rao House	No
2		Gosha Mahal	M.J Market	11KV	IX	3:25	6:48	3:23	All Indication	Pin Insulator flash over at Malakunta Petrol Pump	Arranged B/F on 11KV Osmangunj fdr
3		Santosh Nagar	Chandra Huts	11KV	VIII	4:19	5:46	1:27	EL,OL-Rph	HG fuse blowoff at I.S Sadan	No
4		Ch' Baradari	S.R.T Colony	11KV	III	21:44	22:56	1:12	OL-Rph	Jumper cut at SS	No
1	HYD C	Golconda	Darga Cable	11KV	VII	03.03	06.20	03.17	EL,OL-Bph	Pin Insulator flash over at Pochamma Basti	No
2		Gudimalkapur	Sri Ram Nagar	11KV	VII	04.25	05.55	01.30	EL,OL-Yph	No Visible Fault	No
3		I.T.I Mallepally	V.B.R.I	11KV	VII	12.11	13.29	01.18	EL,OL	Pin Insulator flash over at Prashanth Apts	No
4		Lake View	N.K.M.'s Hotel	11KV	I	13.10	15.00	01.50	All Indication	CT PT fault at Hidox Technology, Erramanil	No
5		Lake View	N.K.M.'s Hotel	11KV	I	13.22	14.55	01.33	OL-R&Bph	Auto Recloser Jumper cut at Pipuls School	No
6		Lake View	N.K.M.'s Hotel	11KV	I	15.08	16.31	01.23	All Indication	Moisture formed in RMU at Erramanzil	Arranged B/F on 11KV Vijaya Hospital fdr
7		Asif Nagar	Padmanabha Nagar	11KV	VII	18.08	19.57	01.49	All Indication	No Visible Fault	At 19:36Hrs partial fdr charged & remaining loads added on 11KV Avalon fdr
8		Indirapark	R.K.Mutt	11KV	I	20.23	21.50	01.27	EL	Pin Insulator flash over at R.K.Mutt	No

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		2		2		2			
6	RR(N)	54	550	1	11	1	11	1	11			
7	RR(E)	168	403		10		10		10			
8	Hyd	194	1044	1	23	1	23	1	23			
	Total	606	3055	2	46	2	46	2	46	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	4	7	4	7	4	7			
2	NLG	144	988		16		16		16			
3	MDK	107	933	1	7	1	7	1	7			
4	SDPT			1	3	1	3	1	3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	6	33	6	33	6	33	0	0	
	Grand Total	1082	6468	8	79	8	79	8	79	0	0	