

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		1		1		1			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988	1	1	1	1	1	1			
3	MDK	107	933									
4	SDPT			2	3	2	3	2	3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>3</b>	<b>5</b>	<b>3</b>	<b>5</b>	<b>3</b>	<b>5</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>3</b>	<b>8</b>	<b>3</b>	<b>8</b>	<b>3</b>	<b>8</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 03.12.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Madgulapally	Agamothkur	33KV	Miryalguda	12.55	16.10	03.15	O/L	33KV insulator failed		-
1	SDPT	Habsipur	Chittapur	33KV	Siddipet	21.00	22.50	01.50		Line Problem		33 KV Pothareddypet Feeder from 132 KV Habsipur SS
2		Musthyal	Cheriyal	33KV	Husnabad	11.30	12.30	01.00		BD (Tree fall in the line)		-

## TSSPDCL - LMRC / Corporate office

## Circle-wise 11KV Breakdowns

Date: 03.12.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	MARIKAL	PC KUNTA	11KV	Narayanapet	14.20	15.20	01.00		Breakdown near HT/LT Crossing due to wind and gale	-
1	NLG	Kandagatla	Guttakinda	11KV	Suryapet	07.00	10.10	03.10	E/L	11Kv Insulator failed	-
1	SDPT	Kodakandla SS	Kodakandla Town	11KV	Gajwel	12.20	13.35	01.25		Bird Fallen on 11 KV line	-
2		Seetharam pally SS	Vellooru	11KV	Gajwel	16.00	18.20	02.20		11 KV line cut	-
3		GAGILLAPUR	VALLAMPATLA	11KV	Husnabad	01.17	08.38	07.21		POLES DAMAGED DUE TO HITING OF LORRY AT THE ROAD SIDE	-
1	RR N	Devarayamjal	DMC	11KV	Medchal	08.15	09.05	00.50	BD	11KV Jumper cut and replaced at Katta Kaluva	-
1	RR E	Chengicherla	My Villas	11KV	Keesara	18.30	19.55	0.059028		11KV Pole damaged due to Lorry dashed at My Villas	-
1	HYD C	Nampally	Bada Masjid	11KV	Mehdipatanam	10.30	12.00	01.30	EL,OL-Rph	Smokes observed in Breaker at SS	Arranged B/F on 11KV Bazarghat fdr