

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	2	1	2	1	2			
2	NLG	144	988		2		2		2			
3	MDK	107	933	2	2	2	2	2	2			
4	SDPT			1	4	1	4	1	4			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	4	10	4	10	4	10	0	0	
	Grand Total	1082	6468	4	12	4	12	4	12	0	0	

TSSPDCL - LMRC / Corporate office

Date: 24.12.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Gadwal	Dharoor	33KV	Gadwal	17.20	18.00	00.40	O/L	Due to Line Phase to Phase Problem	Dharoor	Alternate supply arranged from 33KV Old Gadwal feeder at 18:00Hrs
1	MDK	Kandi	BDL	33KV	Sangareddy	07.31	09.50	02.19		BD due to Jumper cut	BDL	-
2		Bollaram	Bollaram - III	33KV	Patancheru	13.25	14.45	01.20		BD due to Pole Damaged at Obulam Company	Bollaram - III	-
1	SDP	Musthyal	Dhoolmitta	33KV	Husnabad	11.55	12.30	00.35		BD (Tree Branching fall in the Line Near Rampur Villege)	Dhoolmitta	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 24.12.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Gokulnagar	Nandigama	11KV	Narayanapet	08.05	12.05	04.00		Jumper wire cut and fallen on cross arms	-
2		Nancherla	Nancherla	11KV	Narayanapet	09.47	10.47	01.00		11KV insulator puncture	-
1	NLG	Rajapet	Nemila Agl	11KV	Bhongiri	04.00	10.00	06.00	EL/OL	11 kv Insulator failed at Kalluri Narsireddy well near Nemila village.	-
2		Pamanagundla	Pittampally	11KV	Nalgonda	07.15	12.26	05.11	EL/OL	Tree branches fallen on line	-
1	MDK	Bollaram - I	Kythan	11KV	Patancheru	13.30	14.40	01.10		BD due to after petrolling no fault found	-
2		Bollaram - I	Salgutty	11KV	Patancheru	13.30	16.50	03.20		BD due to Pole damaged	-
1	SDP	Markook SS	Markook AGL LC: 22183 Bhaskar CL	11KV	Gajwel	07.20	09.20	02.00		DTR HG fuse wire Burning	-
2		Dommata SS	Gajulapally LC: 10525 Subhash JLM	11KV	Gajwel	14.21	17.52	03.31		DTR Fail	-
3		Thukkapur SS	PS Feeder LC: 7285 Venkat Reddy LM	11KV	Gajwel	10.30	11.30	01.00		Jumper Cut	-
4		Komuravelli	Inapur Agl	11KV	Husnabad	06.00	06.10	00.10		Line cut	-
1	RR E	Cherlapally-IV	Dainatek	11KV	Sainikpuri	02.00	02.50	00.50		11Kv line cut at near Cora Company (Artisan Ravinder)	-
1	HYD C	Golconda	Narayanamma College	11KV	VII	18.48	22.50	04.02	EL,OL-Rph	AB Cable fault at Narayanamma College	At 20:42Hrs added partial loads on 11KV Darga Cable fdr