

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1	4	1	4	1	4			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		5		5		5			
	Total	606	3055	1	11	1	11	1	11	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2	1	2	1	2	1			
2	NLG	144	988	2	29	2	29	2	29			
3	MDK	107	933	1		1		1				
4	SDPT			1	3	1	3	1	3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	6	33	6	33	6	33	0	0	
	Grand Total	1082	6468	7	44	7	44	7	44	0	0	

TSSPDCL - LMRC / Corporate office

Date: 09.02.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Nagarkurnool	Bijnapally	33KV	Nagarkurnool	01.20	06.56	05.36	E/L	Due to Conductor Snapped	Bijnapally	-
2		Nagarkurnool	Rakonda	33KV	Nagarkurnool	00.58	02.55	01.57	O/L	Pin Binding Failed at Manthathi X Road	Rakonda	-
1	NLG	Ramannapet	Yallanki	33KV	Choutuppal	08.12	09.45	01.33	E/L	33kv Jumper Snapped near Ramannapet 132kv Ss	Yallanki	-
2		Suryapet	S.V College	33KV	Suryapet	07.10	11.10	04.00	E/L	Insulator flashover	S.V College	-
1	MDK	Singoor	Mudmanik	33KV	Jogipet	10.20	11.25	01.05		B/D Due to Jumer Cut	Mudmanik	-
1	SDPT	Gajwel	pragnapur	33KV	Gajwel	13.35	14.45	01.10		BD (Due to Rain)	pragnapur	-
1	RR N	132KV DP Pally	33KV Maisammaguda	33KV	Jeedimetla	10.23	13.31	03.08	BD	Kites fallen on the 33KV Line at Double Bed room Houses at Gandhi Maisamma	33KV Maisammaguda	-

TSSPDCL - LMRC / Corporate office

Date: 09.02.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Annasagar	Tatikonda	11KV	Jadcherla	09.00	11.11	02.11		11 KV insulater near Tatikonda (v)	-
1	NLG	Nakrekal	Nomula	11KV	Nalgonda	12.10	13.40	01.30	EL	Insulator failed	-
2		Kanagal	Kanagal (AGL)	11KV	Nalgonda	08.00	09.10	01.10	EL	Insulator failed	-
3		Akaram	Akaram	11KV	Nalgonda	16.00	17.50	01.50	EL	Jumper cut	
4		Turkapally	Hyrjalapuram	11KV	Nalgonda	10.00	11.55	01.55	EL	Disk failure	
5		Edulur	Parada	11KV	Nalgonda	14.00	15.30	01.30	EL	Disk failure	
6		Nampally	M.R.Pally	11KV	Devarakonda	09.30	10.30	01.00	EL	11KV Line Cut	
7		Durajpally	Durajpally Agl	11KV	Suryapet	07.30	09.15	01.45	E/L	Tree branch fallen on the line	
8		Reddygudem	Kothagudem	11KV	Suryapet	11.00	13.30	02.30	E/L	Insulator flashover	
9		Thatipamula	Nandapuram	11KV	Suryapet	12.30	15.20	02.50	E/L	Insulator flashover	
10		Nuthankal	Polumalla	11KV	Suryapet	09.25	11.50	02.25	E/L	Conductor snapped	
11		Keethavarigudem	Velidanda	11KV	Huzurnagar	05.30	05.40	00.10	E/L	Insulator failed	
12		Thogarai	Ganapavram	11KV	Huzurnagar	05.56	06.00	00.04	E/L	Insulator failed	
13		Dircincherla	Narsaigudem	11KV	Huzurnagar	12.00	18.20	06.20	E/L	Insulator failed	
14		Palakeedu	Nagireddygudem	11KV	Huzurnagar	07.30	11.10	03.40	E/L	Insulator failed	
15		Garidepaly	L.B.Nagar	11KV	Huzurnagar	06.05	08.30	02.25	E/L	Insulator failed	
16		Garidepally	Ponugodu	11KV	Huzurnagar	06.10	10.40	04.30	E/L	Insulator failed	
17		Ponugodu	Velidanda	11KV	Huzurnagar	05.45	11.10	05.25	E/L	Jumper Cut	
18		Mellachervu	Venkatrampuram	11KV	Huzurnagar	10.05	10.30	00.25	E/L	11KV conductor snapped	
19		Bollepally	Bollepally	11KV	Bhongir	10.25	11.30	01.05	EL	11KV Insulator Failed near Golla srnivas Well	
20		Alair	Ch.Kandukur	11KV	Bhongir	05.00	09.20	04.20	OL	11kv Line snapped near Ch.Kandukur Village	
21		Alair	Ikkurthy	11KV	Bhongir	03.00	08.30	05.30	EL/OL	11 kv Insulator Failed Near Ikkurthy village. 3 Phase B/d single phase ok	
22		Golankonda	Golankonda	11KV	Bhongir	02.00	08.30	06.30	EL/OL	11 kv Disc failed & 11 kv Insulator failed near Ammanabole village. 3 Phase B/d single phase ok	
23		Golankonda	Vanchyagudem	11KV	Bhongir	03.00	09.00	06.00	EL	11kv Insulator Filed near Vanchagudem Village 3 Phase B/d single phase ok	
24		Mothkur	Town	11KV	Bhongir	09.30	12.40	03.10	OL	11kv Insulator Failed near Mothkur Town	
25		Addagudur	Addagudur Agl	11KV	Bhongir	10.00	13.30	03.30	EL	11kv 2no's Insulators Failed near Addagudur Village	
26		Paladugu	Dattappagudem	11KV	Bhongir	11.20	12.15	00.55	OL	11KV Insulator Failed near Datthappgudem	
27		Gundala	Ramaram	11KV	Bhongir	06.00	10.00	04.00	EL/OL	11kv Insulator Failed near Ramaram Village 3 Phase B/d single phase ok	
28		Suddala	Pallepahad	11KV	Bhongir	02.30	07.00	04.30	EL/OL	16 kva DTR Failed Near Pallepahad Village	
29		Suddala	Anantharam	11KV	Bhongir	10.00	13.00	03.00	EL	11kv Insulator Failed near Anantharam Village	

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	SDPT	Dharmaram	Dharmaram(R.)	11KV	SDPT	00.00	15.00	15.00		HT/LT, same rectified	-
2		Gandipally	Ramavaram Exp	11KV	SDPT	00.50	09.15	08.25		Line fault, same rectified	-
3		Dhoolmitta	Arjunpatla	11KV	SDPT	00.00	13.00	13.00		Insulator failure, same rectified	-
1	RR N	Jeedimetla-I	Maheshwari	11KV	Jeedimetla	05.30	07.30	02.00	EL/OL	11kv line jumper Cut at SS Outside	-
2		Jeedimetla-I	Su-drugs	11KV	Jeedimetla	10.00	11.55	01.55	EL/OL	CTBT Blast at Pavani Industrial	-
3		Jeedimetla-I	JETL	11KV	Jeedimetla	10.00	11.30	01.30	EL/OL	11kv line jumper cut at Tensco Compnay	-
4		Jeedimetla-IV	Tagoure	11KV	Jeedimetla	10.05	12.25	02.20	EL/OL	Tree branchesh Fallen the 11kv line at Tagoure	-
1	RR E	AS Rao Nagar	BSNL	11KV	Habsiguda	11.55	13.27	01.32		11Kv line Ab Switch Opened at Kamal Nagar near Coffe shop Due to crow and fallen and copper patti cut	-
2		Singapur	IT Park	11KV	Keesara	09.25	10.55	01.30		11KV Jumper cut at Saini Properties	-
1	HYD N	Macha Bollarum	Balaji Rice Mill	11KV	C-VI	09.48	11.02	01.14	EL	Kite Sticks fallen on lines at Balaji Rice Mills	-----
2		H.M.T	Sri Sai Colony	11KV	VI	10.12	11.30	01.18	EL	Insulator flash over at Sri Sai Colony	Arranged B/F on 11KV AOL feeder
1	HYD S	Khilwath	Charminar	11KV	III	04.43	05.59	01.16	EL,OL-Bph	AB Cable fault at Silky Ice Cream (3No. DTR's kept off)	
2		Attapur	N.M.Guda OH	11KV	III	15.10	16.15	01.05	EL,OL-Bph	No.3rd Auto Recloser problem at N.M.Guda (At 15:35Hrs partial fdr charged) (25/50Amp)	
1	HYD C	Industrial Area	Barkathpura	11KV	II	14.05	15.16	01.11	EL,OL-Rph	CT PT problem at S.L.Diagnostic	