

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1				1		1 No.33KV Still
2	NLG	144	988		5		5		5			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	5	1	5	0	5	1	0	
	Grand Total	1082	6468	1	7	1	7	0	7	1	0	

TSSPDCL - LMRC / Corporate office

Date: 22.02.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Sri Rangapur	Vijay Neha	33KV	Shadnagar	20.34	00.00	03.26	E/L	Not Rectified	Vijay Neha	-

TSSPDCL - LMRC / Corporate office

Date: 22.02.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Kethepally	Inupamula	11kv	Nalgonda	03.55	06.15	02.20	EL	11KV Jumper Cut	-
2		Akupamula	Lift	11kv	Huzurnagar	07.00	14.00	07.00	EL	Insulator Burent	-
3		Repala	Vijayaraghavapuram	11kv	Huzurnagar	11.55	14.40	02.45	EL	Tree Fall Down on the Line	-
4		Thimareddygudam	Thimareddygudam	11kv	Huzurnagar	14.00	15.30	01.30	EL	Insulator Burent	-
5		Panhangi	Panhangi Agl	11kv	Choutuppal	02.00	06.50	04.50	EL	11kv Insulator failed near Pantnagi Village	-
1	RR N	Chintal	Ganesh Nagar	11kv	Medchal	11.35	13.05	01.30	BD	11KV Cable endkit failed at Honda Show Room Backside, Chintal Main Road (Load added to 11KV Ganesh Nagar feeder)	-
1	HYD N	Clock Tower	Sangeeth	11kv	Clock Tower	17.44	19.10	01.26	EL,OL-Bph	HT Conductor snapped at Royal Reve Hotel	1no DTR kept off