

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044	1		1		1				
	Total	606	3055	1	1	1	1	1	1	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	1	1	1	1	1			
2	NLG	144	988		3		3		3			
3	MDK	107	933	1		1		1				
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	4	2	4	2	4	0	0	
	Grand Total	1082	6468	3	5	3	5	3	5	0	0	

TSSPDCL - LMRC / Corporate office

Date: 13.02.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Sri Rangapur	Vijay Neha	33KV	Shadnagar	20.34 (22.02.2020)	9.50 (23.02.2020)	13.16	E/L	Unfortunatly Lorry Accident	Vijay Neha	-
1	MDK	Bollaram	Bollaram SS - II	33KV	Patancheru	01.30	08.50	07.20		BD due to Tree fallen on line & Conductor snapped, alernet supply aranged from 33KV Shathavahana feeder	Bollaram SS - II	-
1	HYD C	132KV Hussain Sagar	A.C.Guards	33KV	Asif Ngr	00.03	17.10	17.07	OL-Bph	33KV A.C.Guards - Nampally interlinking Cable fault at Opp. Incoming Tax Towers, A.C.Guards Road & 2No. Straight through Joint Kits & 8 Meters Cable provided	A.C.Guards	At 00.13 hrs Loads transferred onto 132KV NIMS SS via 33KV A.C.Guards fdr

## TSSPDCL - LMRC / Corporate office

Date: 13.02.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Rajapur	Mudiredypally	11KV	Jadcherla	06.15	12.00	05.45		11 KV wire cut near Raiahapally	-
1	NLG	Pamanagunda	Pittampally	11KV	Nalgonda	09.00	10.16	01.16	E/L	11Kv Insulator Failed	-
2		Yerkaram	Yerkaram	11KV	Suryapet	13.30	16.00	02.30	E/L	11Kv Line Cut	-
3		Janpahad	Janpahad	11KV	Huzurnagar	09.20	11.00	01.40	E/L	11Kv jumpet cut near 25Kv Transformer	-
1	RR E	IDA Uppal	Kamakshipuram	11KV	Habsiguda	20.18	21.05	00.47		11KV Bunch Cable cut at Dumping Yard & Alternate Supply Arranged from 11KV Srinivasapuram feeder	-