

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		1		1		1			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988	1	2	1	2	1	2			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>2</b>	<b>2</b>	<b>2</b>	<b>2</b>	<b>2</b>	<b>2</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>2</b>	<b>4</b>	<b>2</b>	<b>4</b>	<b>2</b>	<b>4</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 06.12.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Sri Rangapur	Vijay Neha	33kv	Shadnagar	14.16	17.25	03.09	E/L	Pin Baining Replacment	Vijay Neha	-
1	NLG	Wadapally	Janpahad	33kv	Huzurnagar	01.40	07.00	05.20	EL/OL	33Kv Pin Insulater Failed	Janpahad	-

TSSPDCL - LMRC / Corporate office

Date: 06.12.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Tekumatla	Yendlapally	11kv	Suryapet	08.50	10.40	01.50	E/L	11Kv Conductor snapped	-
2		Dirsincherla	Dirsincherla	11kv	Huzurnagar	08.10	10.00	01.50	E/L	11Kv Pin Insulater Failed	-
1	RR E	Vasanthapuri	Venkateshwar Nagar	11kv	Sainikpuri	03.35	05.43	02.08		Pin Insuletor fail on Line Twisting at PVN Colony Charch Opp (AE/OP)	-
1	HYD N	Clock Tower	Station Road	11kv	Clock Tower	19.06	20.28	01.22	EL,OL-Rph	O/G Cable fault	Arranged B/F on 11KV Railway Reservation fdr