

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		14		14		14			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		8		8		8			
	Total	606	3055	0	23	0	23	0	23	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988		2		2		2			
3	MDK	107	933	3	3	3	3	3	3			
4	SDPT			1		1		1				
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	5	5	5	5	5	5	0	0	
	Grand Total	1082	6468	5	28	5	28	5	28	0	0	

TSSPDCL - LMRC / Corporate office

Date: 01.03.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthy	Peddamandadi	33KV	Wanaparthy	07.32	09.16	01.44		33KV Conductor snapped at 220KV Wanaparthy	Peddamandadi	Alternate Supply Arranged From 33KV Kothakota in 132KV SS Thirumalaipally at 9:16Hrs
1	MDK	Kandi	SKOL	33KV	Sangareddy	18.30	22.35	04.05		B/D due to Jumper cut	SKOL	-
2		Gummadidala	AFA	33KV	Patancheru	16.15	18.55	02.40		B/D due to Insulator failure	AFA	-
3		Bollaram	CTO	33KV	Patancheru	19.30	21.15	01.45		B/D due to Disk failure	CTO	-
1	SDP	Angadikistapur	Erravally	33KV	Gajwel	16.34	17.03	00.29		BD (Bird died on wires)	Erravally	-

TSSPDCL - LMRC / Corporate office

Date: 01.03.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Kodur	Kommal	11KV	Suryapet	05.00	07.45	02.45	E/L	11Kv Insulator failed	-
2		Sirikonda	Balluthanda	11KV	Huzurnagar	07.30	10.00	02.30	E/L	11Kv line cut	-
1	MDK	Hadnoora	Town	11KV	Jogipet	19.30	20.30	01.00		B/D due to Tree branches fallen on the line	-
2		Inole	Pedda Kanjarala	11KV	Patancheru	20.00	21.40	01.40		B/D due to Jumper cut	-
3		Bollaram-I	Soubhagya	11KV	Patancheru	10.24	12.11	01.47		B/D due to Jumper cut	-
1	RR N	Aleap	Madhuranagar	11KV	Kukatpally	20.20	21.20	01.00	EL/OL	Tree Branchesh fallen the 11kv line at plot:1110, Doctores Colony	-
2		Vikas	Vikas	11KV	Kukatpally	19.30	21.30	02.00	EL	11kv Disk Failure at Hyrees , Vikas	-
3		Vikas	Volvo	11KV	Kukatpally	19.26	21.35	02.09	EL/OL	11kv Pin Insulater failure at Sai Anuragh Colony	-
4		Somashila	R P Colony	11KV	Kukatpally	19.41	21.30	01.49	EL/OL	Bynding Wire Touched the 11kv line at RP Colony X Raod	-
5		Vijayanagar	Allwyn Colony	11KV	Kukatpally	20.20	21.25	01.05	EL/OL	11kv line Jumper Cut at SSB temple , Allwyn Colony	-
6		Shemshiguda	Last busStop	11KV	Kukatpally	19.45	21.15	01.30	EL	11kv Disk Failure at Allwyn Colony Last BusStop	-
7		Bhagyanagar	Medchal	11KV	Kukatpally	19.39	22.35	02.56	EL	11kv Disk Failure at opp:Sai Baba Temple Bhagyanagar Colony	-
8		Jeedimetla-IV	Tagoure	11KV	Jeedimetla	19.50	21.54	02.04	EL/OL	TRIPPED ON EL/OL Indication,Line petroling Nifalt {Due To Rain }	-
9		Jeedimetla-III	USP Oraganic	11KV	Jeedimetla	19.44	22.05	02.21	EL/OL	11kv AB Cable failure at Athulitha Chemical Company	-
10		Jeedimetla -I	Thirumala	11KV	Jeedimetla	19.35	21.35	02.00	EL/OL	TRIPPED ON EL/OL Indication,{Due to Rain }	-
11		UMCC	Mahadevpuram	11KV	Medchal	20.03	20.33	00.30	EL	100KVA DTR Post of Insulator failed at Yandamuri Layout	-
12		Jagathgirigutta	IDA	11KV	Medchal	20.00	20.50	00.50	EL	11KV Cable earthing failed at Sanjay Gandhi nagar	-
13		Myatsh	BVRIT	11KV	Kukatpally	19.45	21.08	01.23	EL/OL	line petroling No Visble falt {Due to Rain }	-
14		Thumkunta	Thumkunta	11KV	Medchal	07.50	09.50	02.00	EL/OL	Bird fallen on the 11KV Line at Rambabu Poultry Farm	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR E	Uppal	GKSR	11KV	Habsiguda	20.25	21.25	01.00		Tripped on EL/OL (due to rain) line petroling done no visiable falt found	-
1	HYD N	Gunrock	Thirumalgiri	11KV	C-VI	20.02	21.25	01.23	EL	DTR HG fuse set flash over at opp.Max & Breaker problem at SS	Arranged B/F on 11KV Surya Enclave fdr
2		Adda Gutta	Thukaram Gate	11KV	C-VI	20.10	21.50	01.40	EL	Tree fallen on lines at Banjara Arcade	-----
3		Road No.12	Road No.12	11KV	X	20.38	21.40	01.02	EL	No Visible Fault	-----
4		Zamistanpur	Sanjeevaiah Puram	11KV	V	21.07	22.16	01.09	EL	Jumper cut on double pole structure at Parsi Gutta	-----
5		Gymkhana	Sikh Village	11KV	C-VI	20.30	22.10	01.40	EL	Pin Insulator flash over at Imperial Garden	-----
6		Gymkhana	Rani Bagh	11KV	C-VI	19.50	22.20	02.30	EL	No Visible Fault	Arranged B/F on 11KV Pared Ground fdr
7		Chinthal	Caption Gas	11KV	VI	20.10	22.50	02.40	EL	DTR Fault at Kavitha Industries	-----
1	HYD C	Chilkaiguda	Parsi Gutta	11KV	II	20.10	21.40	01.30	EL	Cloth fallen on lines at Krishnaveni School	-