

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	1	0	1	0	1	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		1		1		1			
3	MDK	107	933									
4	SDPT				3		3		3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	4	0	4	0	4	0	0	
	Grand Total	1082	6468	0	5	0	5	0	5	0	0	



TSSPDCL - LMRC / Corporate office

Date: 24.03.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Addagudur	Addagudur Agl	11KV	Bhongir	4:00	9:45	5:45	EL	11KV Insulator failed	No
1	SDPT	Bejjanki	Cotton Mill	11KV	Husnabad	9:05	11:35	2:30		Line cut	No
2		Bejjanki	Regulapally	11KV	Husnabad	10.50	11.50	01.00		Pole damaged	No
3		Cherial Town	Cherial-Town	11KV	Husnabad	10.45	11.30	00.45		HT/LT Conductor touched	No
1	HYD S	Kulsumpura	Gandi Hanuman	11KV	IX	08.22	10.11	01.49	EL	AB Cable fault at Bilal Masjid	No