

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044		2		2		2			
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	4	8	4	4	4	4			
2	NLG	144	988	1	2	1	2	1	2			
3	MDK	107	933	2		2		1		1		1 No. 33kv still
4	SDPT			1	1	1	1	1	1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	8	11	8	7	7	7	1	0	
	Grand Total	1082	6468	8	14	8	10	7	10	1	0	

## TSSPDCL - LMRC / Corporate office

## Circle-wise 33KV Breakdowns

Date: 07.05.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Makthal	Narva	33kv	Narayanpet	03.50	06.15	02.25	E/L	Due to Rain 11KV Poles damage, Induction purpose	Narva	-
2		Makthal	Krishna	33kv	Narayanpet	03.50	06.45	02.55	E/L	Tree branches follen on the Line	Krishna	-
3		Kosgi	Surayapally	33kv	Narayanpet	02.14	07.20	05.06	E/L	for Pin Insulator Failed Near Challapur	Surayapally	-
4		Marrikal	Kondapur	33kv	Narayanpet	19.07	19.52	00.45	E/L	Pin Insulator Failed	Kondapur	-
1	NLG	Mattampally	B.N.Thanda	33kv	Huzurnagar	17.50	19.07	01.17	EL/OL	33KVJumpet Cut	B.N.Thanda	-
1	MDK	Narayankhed	Sirgapur	33kv	Jogipet	16.35	20.10	03.35		B/D Due to Insulator Failure	Sirgapur	-
2		Narayankhed	Kalher	33kv	Jogipet	21.15	00.00	02.45		B/D Due to Still Continuo	Kalher	-
1	SDPT	Shanigaram	Shanigaram	33kv	Husnabad	04.45	06.00	01.15		BD ( Due to AB switch opened )	Shanigaram	

## TSSPDCL - LMRC / Corporate office

## Circle-wise 11KV Breakdowns

Date: 07.05.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Pedda Revally	Chinna Revally	11kv	Jadcherla	00.00	17.25	17.25		Poles Damaged near Pochammagadda thanda	-
2		Pedda Revally	Bodagutta	11kv	Jadcherla	01.00	07.37	06.37		Poles Damaged near Boda Janampet	-
3		Balanagar	Gouthapur	11kv	Jadcherla	00.00	17.00	17.00		Poles Damaged near Gouthapur	-
4		Nawabpet	Rudraram	11kv	Jadcherla	00.00	15.30	15.30		Poles Damaged near Rukkampally	-
5		Nawabpet	Lokirew	11kv	Jadcherla	11.06	12.15	01.09		11kv Disk fail near Lokirew	-
6		Marrikal	Malkapur	11kv	Jadcherla	10.20	11.40	01.20		11KV Wire cut near Malkapur	-
7		Thirumalapur	Thirumalapur	11kv	Jadcherla	08.26	11.40	03.14		11kv Insulator fail near Thirumalapur	-
8		Ponnakal	Ponnakal	11kv	Jadcherla	10.30	11.30	01.00		11kv Jumper cut near Ponnakal	-
1	NLG	Reddygudem	Kothagudem	11kv	Suryapet	05.00	08.30	03.30	EL	Insulator failed	-
2		Palakeedu	Janpahad indl	11kv	Huzurnagar	05.00	07.45	02.45	EL	11 KV LINE SNAPPED	-
1	SDPT	Pandilla	Pandilla Rural	11kv	Husnabad	08.10	10.00	01.50		Insulator failed	-
1	RR N	Yellampet	IDA Yellampet	11kv	Medchal	14.26	16.10	01.44	BD	160 KVA DTR Brass Patti cut Fallen on AB Switch at Yellampet Village	-
1		Gunrock	Tirumalgiri	11kv	C-VI	10.00	11.20	01.20	OL-R&Bph	Jumper cut at LIC Building	-----

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
2	HYD N	Macha Bollaram	Fatherbalaiah Nagar	11kv	C-VI	23.23	02.26	03.03	EL	Tree fallen on lines at Tirumala Hills	(At 00:15Hrs partial fdr charged & remaining loads added on 11KV Sai Reddy Nagar fdr