

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		3		3		3			
8	Hyd	194	1044	1	3	1	3	1	3			
	Total	606	3055	1	7	1	7	1	7	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2	1	2	1	2	1			
2	NLG	144	988		10		10		10			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	11	2	11	2	11	0	0	
	Grand Total	1082	6468	3	18	3	18	3	18	0	0	

TSSPDCL - LMRC / Corporate office

Date: 20.05.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Maddur	Vepoor	33kv	Narayanapet	23.20	06.00	06.40	E/L	Due to pin insulator failed	Vepoor	-
2		Ileeza	Gattu	33kv	Gadwal	20.15	21.45	01.30	E/L	Due to 33KV Breker Problem at 132KV SS & Alternate Supply Arranged to 33KV Mitta Doddy Feeder at 21:45Hrs	Gattu	-
1	HYD N	132KV Jubilee Hills	Madhapur (PTR-1&4)	33kv	Jubilee Hills	10.40	10.45	00.05	EL,OL-Yph	Cable damaged by unknown person at Jena Sena Party Office	Madhapur (PTR-1&4)	Loads transferred onto 132KV Madhapur SS via 33KV Madhapur-I

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 20.05.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Karkonda	Rudraram	11kv	Jadcherla	13.21	15.06	01.45		HT/LT Near Rudraram	-
1	NLG	Kanagal	Kanagal town	11kv	Nalgonda	03.20	07.00	03.40	E/L	11KV jumper cut	-
2		Chervugattu	Sheribaigudem	11kv	Nalgonda	08.40	10.55	02.15	E/L	11KV jumper cut	-
3		Eduloor	Parada	11kv	Nalgonda	14.10	15.25	01.15	E/L	11KV insulator failed	-
4		Aregudem	Ogodu	11kv	Nalgonda	14.05	14.50	00.45	E/L	Insulator failed	
5		Arlagaddagudem	Mangalapally	11kv	Nalgonda	12.30	17.20	04.50	E/L	11KV jumper cut	
6		Shettipalem	Shettipalem	11kv	Miryalaguda	04.45	06.18	01.33	E/L	Insulator failed	
7		Nuthankal	Nuthankal Agl	11kv	Suryapet	02.20	05.30	03.10	EL	Insulator failed	-
8		Gondiryala	Chimiryala	11kv	Huzurnagar	06.00	08.15	02.15	EL	11 KV LINE SNAPPED	-
9		Azeempet	Repaka	11kv	Bhongir	00.30	08.40	08.10	EL/OL	11 kv Line snapped at Muthyalamma temple Near Repaka village.	-
10		Ramannapet	Janampally	11kv	Choutuppal	08.45	10.52	02.07	EL/OL	11 kv Line snapped near Janampally village	-
1	RR N	Shameerpet	Devaryamzal	11kv	Medchal	13.45	17.05	03.20		Tree branches fallen on lines.	-
1	RR E	Narapally	LM Shankar	11kv	Keesara	10.30	11.40	01.10		11KV Line Snapped at ORR	-
2		P&T colony	Chengicehrla	11kv	Keesara	11.15	13.05	01.50		11KV Line touch to pole at Sri sri colony	-
3		Chengicherla	Chengicherla	11kv	Keesara	09.32	10.39	01.07		T/F brash patti cut at MLR Colony Pochamma temple	-
1	HYD N	Marredpally	Mahindra Hills	11kv	C-VI	13.44	15.10	01.26	EL	Disc Insulator flash over & 1st Sectionalizer fault at Thanvi Hotel	
1	HYD C	Nampally	FAPCCI	11kv	VII	06.08	07.13	01.05	EL	Tree branches fallen on lines at FAPCCI Building	
2		ITI Mallepally	V.B.R.I.	11kv	VII	12.05	13.13	01.08	EL,OL	HT/LT Line snapped near SS	