

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044									
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988	1	1	1	1	1	1			
3	MDK	107	933	1	1	1	1	1	1			
4	SDPT			1	7	1	7	1	7			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>3</b>	<b>10</b>	<b>3</b>	<b>10</b>	<b>3</b>	<b>10</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>3</b>	<b>10</b>	<b>3</b>	<b>10</b>	<b>3</b>	<b>10</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 22.05.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Mattampally	Pedaveedu	33KV	Huzurnagar	00.00	10.00	10.00	EL/OL	Due to CT Failure in 132Kv	Pedaveedu	-
1	MDK	Gummadidala	AFA	33KV	Patancheru	16.15	18.58	02.43		BD Due to Service PT Failed	AFA	-
1	SDPT	Gajwel	Jagadevpur	33KV	Gajwel	15.00	17.10	02.10		Pin insulater Replacement	Jagadevpur	-

## TSSPDCL - LMRC / Corporate office

## Circle-wise 11KV Breakdowns

Date: 22.05.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	K V Pet	Bandameedipally	11KV	Jadcherla	09.30	10.55	01.25		11Kv Jumper Cut Near Bandameedipally(Vi).	-
1	NLG	Ravulapally	Thurpugudem	11KV	Suryapeta	06.00	09.30	03.30	EL	Insulator flashover	-
1	MDK	Bollaram - II	Rupa	11KV	Patancheru	05.37	07.47	02.10		BD due to conductor Snapped	-
1	SDPT	Chandlapur	Gangapur	11KV	Siddipet	13.10	16.00	02.50		B/D 11 KV line netting & LC No.15890	-
2		Ramancha	Ramancha	11KV	Siddipet	13.00	15.40	02.40		B/D Insulater fail & LC.No.10383	-
3		Raghothampally	Gosanpally	11KV	Siddipet	00.00	09.25	09.25		B/D Insulater fail due to rat & LC.No.13692	-
4		Habsipur	Dharmaram	11KV	Siddipet	12.38	14.20	01.42		B/D Tree fall on the line & LC No.4337	-
5		DR Pally SS	DR Pally Feeder	11KV	Gajwel	05.30	06.45	01.15		11KV Line cutting	-
6		Kistapur SS	Banjarpally Feeder LC 20153	11KV	Gajwel	06.35	09.20	02.45		11 KV Wire Cutting	-
7		Koheda	Kurella	11KV	Husnabad	09.20	10.22	01.02		Insulator Failed	-