

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	3	1	3	1	3	1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	3	3	3	3	3	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1						1No 33KV feeder still
2	NLG	144	988		5		5		5			
3	MDK	107	933									
4	SDPT				6		6		6			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	11	1	11	0	11	0	0	
	Grand Total	1082	6468	4	14	4	14	3	14	0	0	

TSSPDCL - LMRC / Corporate office

Date: 13.11.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Balanagar	Surya Jyothi	33KV	Jadcherla	19.45	23.15	03.30	E/L&O/L	Cable Failed & Rectified at Gunded village		No
2		Balanagar	Surya Jyothi	33KV	Jadcherla	23.15		00.45	E/L&O/L	Not Rectified Due to Cable Blast at Gunded Village		No
1	RR N	132KV LGM Pet	33KV Aliabad	33KV	Medchal	12.20	13.45	01.25		33KV Y Phase Jumper Cut & Replaced in Aliabad SS		-
2		132KV LGM Pet	33KV MN Park	33KV	Medchal	05.00	07.31	02.31		No Fault		-
3		132KV Medchal	33KV Steel Mill	33KV	Medchal	09.35	11.35	02.00		Internal Problem in Steel Mill Company		-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 13.11.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Pamanagundla	Yerasanigudem	11KV	Nalgonda	04.30	08.13	03.43	E/L	11KV Jumper cut	-
2		Akaram	Vaddipamula	11KV	Nalgonda	08.16	10.30	02.14	E/L	Moment fault	-
3		CH.Annaram	Thottavarigudem	11KV	Nalgonda	02.20	12.02	09.42	E/L	11KV Insulator failed	-
4		Indugula	Mallapurajugudem	11KV	Nalgonda	10.30	14.00	03.30	E/L	11KV Jumper cut	-
5		Mukundapuram	Chandupatla	11KV	Suryapet	08.50	10.25	01.35	E/L	Bird fallen on the 11Kv Line	-
1	SDPT	Thadkapally	venkatapur	11KV	Siddipet	07.35	08.10	00.35		B/D Insulator failure	-
2		Thornal	Thornal	11KV	Siddipet	16.40	17.45	01.05		B/D Insulator failure	-
3		Akunoor	Dommata	11KV	Husnabad	17.40	19.30	01.50		Tree Branch fallen on the line	-
4		Cherial Town	Rollabanda	11KV	Husnabad	10.50	11.20	00.30		Jumper Cut	-
5		Chityala	Dommata	11KV	Husnabad	10.20	11.30	01.10		Jumper Cut	-
6		Komuravelly	Kistampet	11KV	Husnabad	17.35	18.00	00.25		Bird fallen on the line	-
1	RR N	ICICI	Unique - I	11KV	Medchal	18.13	19.13	01.00		11KV Adama feeder CTPT failed at Adama Company	-
1	RR E	VP Nagar	Brundhavan Colony	11KV	Sainikpuri	08.38	09.28	00.50		Ground Patrolling Done But No Fault Found (LM Chandra Shekar)	-
1	HYD N	Gunrock	Medchal	11KV	Bowenpally	15.50	17.06	01.16	EL,OL	HT Line snapped at Lotus Pond	-