

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044		2		2		2			
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2	4	2	4	2	4			
2	NLG	144	988		8		8		8			
3	MDK	107	933	1	0	1	0	1	0			
4	SDPT			1	4	1	4	1	4			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	4	16	4	16	4	16	0	0	
	Grand Total	1082	6468	4	19	4	19	4	19	0	0	

TSSPDCL - LMRC / Corporate office

Date: 03.09.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Gadwal	Nandinne	33KV	Gadwal	09.25	13.05	03.40	E/L	Insulator Damaged at Peddapad		Isolator open at Peddapad at 11:35Hrs.
2		Alampur	Shantinagar-1	33KV	Gadwal	16.44	20.25	03.41	E/L	Tree Fallen on the Line		Alternate Supply Arranged From Shantinagar-2 at 20:25Hrs.
1	MDK	Kandi	BDL	33KV	Sangareddy	14.25	21.20	06.55		BD Due to Pin Insulater Failed		-
1	SDPT	Habsipur	Chittapur	33KV	Siddipet	23:11 (02.09.2020)	01.30	02.19		BD (Insulator Failure)		-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 03.09.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Midjil	Veljal	11KV	Jadcherla	19.30	10.30	15.00		11KV Disc Fail Near Veljal (V)	-
2		Karkonda	Khanapur	11KV	Jadcherla	23.00	10.47	11.47		11KV Disc Fail Near Khanapur (V)	-
3		Damrgidda	Sajnapur	11KV	Narayanapet	12.45	13.50	01.05		11KV Conductor snapped and fallen on the LT AB Cable	-
4		Marikal	Madwar	11KV	Narayanapet	09.23	09.40	00.17		Heavy gale and wind	-
1	NLG	Aitipamula	Gangadevigudem	11KV	Nalgonda	11.20	16.15	04.55	EL	11KV insulator failed	-
2		Kathepally	Kasanagode	11KV	Nalgonda	06.10	11.50	05.40	EL	11KV insulator failed	-
3		Palem	Ogodu	11KV	Nalgonda	05.20	10.00	04.40	EL	11KV jumper cut	-
4		Edulagudem	Housing Board Colony	11KV	Miryalaguda	17.30	18.30	01.00	EL	Tree Perch Touched and Conductor Snapped	-
5		Mukundapuram	Dacharam	11KV	Huzurnagar	03.00	07.00	04.00	EL	11 KV LINE SNAPPED	-
6		Bollepally	Jampally	11KV	Bhongir	10.50	12.00	01.10	EL	11kv Insulator Failed	-
7		Suddala	Theriyala	11KV	Bhongir	04.00	08.00	04.00	EL	11 kv Insulator failed	-
8		Jai kesaram	Assonigudem	11KV	Choutuppal	23.02	15.02	14.02	EL	Palm Tree Fallen at Line & 11kv Pole Damged	-
1	SDPT	JAGADEVPUR	DOULAPUR	11KV	Gajwel	22.20	10.55	12.35		11KV Disc failure	-
2		GANESHPALLY	GANESHPALLY	11KV	Gajwel	13:42	14:05	00.25		insulator failure	-
3		Dulmita	Jalapally	11KV	Husnabad	17.10	18.10	01.00		No Visible fault	-
4		cherial T	cherial T	11KV	Husnabad	17.45	18.10	00.25		insulator failure	-
1	RR N	Kandlakoya	Kandlakoya	11KV	Medchal	00.50	03.40	02.50	BD	Due to Breaker Problem & Load added to 11KV CMR feeder	-
1	HYD S	Gosha Mahal	Gosha Mahal Road	11KV	Begumbazar	12.12	13.35	01.23	EL	Breaker HG fuse not standing	Arranged B/F on 11KV Begum Bazar feeder
2		Hyderguda	W.S Colony	11KV	Charminar	15.25	17.10	01.45	EL	2No. Cable End Kits failed & 2No. Pin Insulators flash over at Golden Palace	-