

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	2	3	2	3	2	3			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		2		2		2			
	Total	606	3055	2	6	2	6	2	6	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	5	1	4	1	4	1			1No 33KV Feeder still
2	NLG	144	988		6		6		6			
3	MDK	107	933		2	5	2	5	2			
4	SDPT				21	2	21	2	21			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	5	30	11	30	11	30	0	0	
	Grand Total	1082	6468	7	36	13	36	13	36	0	0	

TSSPDCL - LMRC / Corporate office

Date: 18.09.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Maddur	Maddur	11KV	Narayanapet	07.50	08.58	01.08	EL	HG Fuse Failed at Maddur SS		NO
2		Shadnagar	Mogiligidda	11KV	Shadnagar	07.45	11.15	03.30	EL	No Visible Fault was Found		NO
3		Kothur	PNG	11KV	Shadnagar	16.16	23.00	06.44	EL	Due to Heavy Rain & Insulator Replacement at Rangapur Village		NO
4		Kothur	Thimmapur	11KV	Shadnagar	16.10	23.52	07.42	EL	Due to Heavy Rain & Jumper Replacment at 132KV SS & 5 Nos Insulator Replacement at Pinjerla Road		NO
5		Kothur	Saint Gobain	11KV	Shadnagar	18.32		05.28	EL	Not Rectified		NO
1	RR N	132KV LGM Pet	33KV Aliabad	11KV	Medchal	15.45	17.26	01.41	EL	Tree fallen on the 33KV Line at Aliabad Village		-
2		132KV Medchal	33KV Medchal-I	11KV	Medchal	17.45	19.45	02.00	EL	Tree Branches fallen on the 33KV Line at Kandlakoya		-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 18.09.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Midjil	Munnanor	11KV	Jadcherla	11.00	13.40	02.40		11 KV insulater fail near Vadyal (v)	-
1	NLG	Wadapally	Damarcherla	11KV	Miryalguda	16.40	18.40	02.00	EL/OL	11Kv Line Snpped	-
2		Cherukupally	Cherukupally	11KV	Devarakonda	15.15	16.30	01.15	E/L	11KV Line Cut	-
3		Nadigudem	Krishnanagar	11KV	Huzurnagar	03.40	06.50	03.10	E/L	11Kv Line Snpped	-
4		Palakeedu	Nagireddy gudem	11KV	Huzurnagar	04.00	07.30	03.30	E/L	11Kv Line Snpped	-
5		Rajapeta	Renikunta Agl	11KV	Bhongir	07.30	09.59	02.29	EL/OL	11kv Insulator failed at Moddula . Balanarsaiah well near Renikunta (V)	-
6		Koyyalagudem	Dothigudem Indl	11KV	Choutuppal	03.50	09.45	05.55	EL/OL	11kv line snapped near Dothigudem (V)	-
1	MDK	Gaddapotharam -II	Apex	11KV	Patancheru	06.50	09.30	02.40		BD due to Conductor snapped	-
2		Dundigal	Jinnaram	11KV	Patancheru	14.20	15.20	01.00		BD due to Disk failed	-
1	SDPT	Jangapally	Jangapally	11KV	Siddipet	16.52	18.10	01.18		JUMPER CUT	-
2		Peddachikode	Kammarpally	11KV	Siddipet	09.00	11.58	02.58		B/D Insulater failed LC No.0662	
3		Gurralagondi	Malyal	11KV	Siddipet	17.13	17.50	00.37		B/D Insulater failed LC No.16702	
4		Mustabad X Road	Gadicherlapally	11KV	Siddipet	16.25	19.00	02.35		B/D AB Switch problem	
5		GAJWEL & PREGNAPUR	MUTRAJ PALLY AGL (LC.NO:6258) BALIYA NAYAK.LI	11KV	Gajwel	12.15	15.47	03.32		DISC FAILED	
6		PAMULAPARTHI	PAMULAPARTHI(L C.NO:	11KV	Gajwel	7:00	11:00	4:00		JUMPER CUT	
7		NACHARAM	MADHARAM (LC.NO:19079) RAMULU.CL	11KV	Gajwel	13:00	14:30	01.30		DISC FAILED	
8		GOWRARAM	PATHUR (LC.NO:)	11KV	Gajwel	17:50	TILL			Tree Branches fallen on 11 kv Line	
9		GOWRARAM	GOWRAMA AGL (LC.NO:40372) KISTAIAH.LM	11KV	Gajwel	18:20	19:30	01.10		Tree Branches fallen on 11 kv Line	
10		DUDEDEA	RAMPALLY & INDUSTRIAL (LC.NO:21355) ILAIAH.CL	11KV	Gajwel	17:00	20:00	3:00		DISC FAILED & Tree Fallen on the Line	
11		MUBARASPUR	THIRUMALAPUR (LC.NO:898) B. SRINIVAS.CL	11KV	Gajwel	07.15	07.56	00.41		DTR WORK	
12		MD SHAPUR	INDURIYAL (LC.NO:)	11KV	Gajwel	12.00	17.00	05.00		At Machan pally road Jumper Opend	
13		DOULTHABAD	LINGARAJ PALLY (LC.NO:3195)	11KV	Gajwel	12.50	13.39	00.49		JUMPER OPEND	
14		Pandilla	Potlapally	11KV	Husnabad	09.20	10.55	01.35		Insulator failure, same rectified.	-
15		Thotapally	Gandinagar	11KV	Husnabad	01.00	06.00	05.00		Jumper cut	-
16		Thotapally	Thotapally Agl	11KV	Husnabad	10.49	11.26	00.37		Insulator failure, same rectified.	-
17		Akkannapet	Pakilnayak Thanda	11KV	Husnabad	13.00	15.10	02.10		Insulator failure, same rectified.	-
18		Guruvannapet	Posanpally	11KV	Husnabad	08.19	10.26	02.07		HT/LT, same rectified	-
19		Guruvannapet	Tapaspally	11KV	Husnabad	16.00	17.20	01.20		Line fault, same rectified.	
20		Komuravelly	Inapur Agl	11KV	Husnabad	17.20	19.20	02.00		HT/LT, same rectified	
21		Nagapuri	Kadavergu	11KV	Husnabad	17.20	19.20	02.00		Disk failure, same rectified	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR N	Aliabad	HBL	11KV	Medchal	17.10	21.10	04.00	EL	11KV Post Insulator failed and replaced in SS	-
2		Aliabad	Aliabad	11KV	Medchal	17.10	21.10	04.00	EL/OL	11KV Pin Insulator Failed and replaced at wines, Aliabad	-
3		Petbasheerabad	GBR Club	11KV	Medchal	14.15	15.30	01.15	EL	Pin Insulator failed at Srikanth Nursery	-
1	RR E	Keesara	Cheryala	11KV	Keesara	16.50	18.50	02.00		Tree fallen on 11kv line at Vekalanggulla colony	-
1	HYD N	Jubilee Hills	A.O.U	11KV	X	01.10	02.18	01.08	EL,OL-Rph	No Visible Fault	-
2		Gymkhana	Mud Fort	11KV	C-VI	15.40	16.50	01.10	EL,OL-Y&Bph	R.M.U fault near Contonment Work Shop	-