

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550	1	15	1	15	1	15			
7	RR(E)	168	403		18		18		18			
8	Hyd	194	1044		11		11		11			
	Total	606	3055	1	45	1	45	1	45	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	6	13	6	13	6	13			
2	NLG	144	988		20		20		20			
3	MDK	107	933	3	2	3	2	3	2			
4	SDPT				25		25		25			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	9	60	9	60	9	60	0	0	
	Grand Total	1082	6468	10	105	10	105	10	105	0	0	

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Makthal	Jaklair	33KV	Narayanapet	07.40	11.10	03.30	E/L	Tree Fallen on the line and removed near Kachvar (V)	Jaklair	No
2		Makthal	Gudeballore	33KV	Narayanapet	00.00	01.55	01.55		Due to Heavy Rain	Gudeballore	No
3		Gadwal	Oil Seeds	33KV	Gadwal	00.00	09.05	09.05		Insulator Damaged at Veerapur SS	Oil Seeds	No
4		Gadwal	Gadwal New	33KV	Gadwal	3:55	7:15	3:20	E/L	LA Blast near 132KV SS	Gadwal New	No
5		Achampet	Veltoor	33KV	Nagarkurnool	7:25	13:05	5:40		Insulator Damaged at Pulijalla (vi)	Veltoor	No
6		Kothur	Thimmapur	33KV	Shadnagar	00.09	09.58	09.49	E/L	Insulator Damaged at Penjaerla Road	Thimmapur	No
1	MDK	Kandi	BDL	33KV	Sangareddy	5:20	14:15	8:55		BD due to Pin Insulator failed	BDL	No
2		Kandi	ACE Tyres	33KV	Sangareddy	15.30	18.40	03.10		BD due to Insulator failed	ACE Tyres	
3		Gummadidala	Gummadidala	33KV	Patancheru	14.20	16.35	02.15		BD due to Tree branches fallen on line	Gummadidala	No
1	RR N	132KV Medchal	Jeedimetla-III	33KV	Medchal	15:40	16:20	0:40		Tree Fallen on the 33KV Line at Kompally	Jeedimetla-III	No

