

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403									
8	Hyd	194	1044									
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	3	1	3	1	3			
2	NLG	144	988		7		7		7			
3	MDK	107	933	5		5		5				
4	SDPT				3		3		3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	6	13	6	13	6	13	0	0	
	Grand Total	1082	6468	6	15	6	15	6	15	0	0	

TSSPDCL - LMRC / Corporate office

Date: 28.04.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Midjil	Velugomula	33KV	Jadcherla	18.50	20.50	02.00	E/L	for Insulator fail near Insulator Replacement Ranipet (vi)	Velugomula	No
1	MDK	Zaheerabad	Mungi	33KV	Zaheerabad	2:30	11:00	8:30		B/D Due to Pin Insulator Failure	Mungi	No
2		Kandi	Bharath Strips	33KV	Sangareddy	06.10	13.55	07.45		B/D Due to 33KV Signode feeder Conductor Snapped at line	Bharath Strips	No
3		Kandi	BDL	33KV	Sangareddy	06.10	13.50	07.40		B/D Due to 33KV Signode feeder Conductor Snapped at line	BDL	No
4		Kandi	Alkabeer	33KV	Sangareddy	06.10	14.00	07.50		B/D Due to 33KV Signode feeder Conductor Snapped at line	Alkabeer	No
5		Kandi	ITW Signode	33KV	Sangareddy	6:10	14:00	7:50		B/D Due to 33KV Signode feeder Conductor Snapped at line	ITW Signode	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Gudeballore	CHECKPOST	11KV	Narayanapet	07.30	10.30	03.00		breakdown due to 11kv line cut at checkpost	No
2		MARIKAL	APPAMPALLY	11KV	Narayanapet	07.23	13.13	05.50		breakdown due to 11kv line cut at appampally vlg	No
3		VENNACHEDU	LINGAIPALLY	11KV	Narayanapet	08.30	12.28	03.58		breakdown due to 11kv line cut at boispally vlg	No
1	NLG	Ghanpur	Polkampally	11KV	Devarakonda	13:45	16:05	2:20	EL	Tree fallen on the line	No
2		Pulichelra	Pulicherla	11KV	Miryalaguda	10.50	11.30	00.40	EL	11KV Disc failed near village	No
3		Utlapaly	Kalwapally	11KV	Miryalaguda	09.53	11.25	01.32	EL	11KV pin insulator failed	No
4		Mukundapuram	Chandupatla	11KV	Suryapet	06.00	09.35	03.35	EL	Conductor snapped	No
5		Reddygudem	Kukkadam	11KV	Suryapet	03.30	06.00	02.30	EL	Insulator failed	No
6		Gondiryala	Chimiryala	11KV	Huzurnagar	06.40	08.00	01.20	EL	11 KV Line snapped	No
7		Ananthagiri	Mogalaikota	11KV	Huzurnagar	0:30	5:00	4:30	EL	11 KV Line snapped	No
1	SDPT	Gurjakunta	Gurjakunta Agl	11KV	Husnabad	9:00	12:20	3:20		Insulator Burst	No
2		NEMTUR	NEMTUR	11KV	Gajwel	09.41	10.44	01.03		Conductor snapped	No
3		MD SHAPUR	LINGAREDDYPALLY THANDA	11KV	Gajwel	16.55	17.43	00.48		63 KVA DTR failed	No
1	RR N	Rajabollaram	Rajabollaram Thanda	11KV	Medchal	7:30	9:19	1:49		Bird fallen on the 11KV Line at Rajabollaram Thanda	No
2		Gowdavelly	Ayodya	11KV	Medchal	17.50	19.50	02.00		11KV Pin Insulator failed at Yashoda Clinic	No