

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		2				
2	NLG	144	988		3		3		3			
3	MDK	107	933		1		1		1			
4	SDPT				3		3		3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	7	2	7	2	7	0	0	
	Grand Total	1082	6468	2	9	2	9	2	9	0	0	

TSSPDCL - LMRC / Corporate office

Date: 10.01.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthy	Narsaipally	33KV	Wanaparthy	14.26	17.09	02.43	E/L&O/L	Y Phase Jumper Snapped Back Side of Sai Baba Temple at Metpally	Narsaipally	No
2		Nagarkurnool	Rakonda	33KV	Nagarkurnool	13.05	15.25	02.20	E/L&O/L	Due to CT Oil Lequage	Rakonda	Alternate Supply Arranged From Peddakothapally at 15:25Hrs

TSSPDCL - LMRC / Corporate office

Date: 10.01.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Reddygudem	Kukkadam	11KV	Suryapet	5:00	7:15	2:15	E/L	Insulator failed	No
2		Peddapadishala	Thurkashapuram	11KV	Bhongir	05.00	10.30	05.30	EL/OL	11kv Insulator Failed near Thurkushapur Village	No
3		Tekulasomaram	Edulagudem	11KV	Choutuppal	07.30	12.29	04.59	EL/OL	11kv Insulator Failed near Edulagudem Village	No
1	MDK	Bonthapally	Jaishenkar	11KV	Patancheru	9:15	11:50	2:35		B/D Due to Monkey Fallen on the line	No
1	SDPT	Guruvannapet	Posanpally	11KV	Husnabad	13:45	14:45	1:00		Insulator failed	Posanpally
2		Chityal	Thadoor	11KV	Husnabad	14.45	18.40	03.55		Conductor snapped	Thadoor
3		Peddakodur	Mandapally	11KV	Siddipet	12.30	13.30	01.00		B/D-Snake came at HG fuse side-Now rectified	Mandapally
1	RR E	IDA Uppal	Metro	11KV	Habsiguda	6:58	9:38	2:40		Cable failed of Metro feeder	Taken back feeding to Navbharath feeder
1	HYD N	Addagutta	Addagutta	11KV	C-VI	17.07	18.10	01.03	EL	Breaker problem at SS	Arranged B/F on 11KV Tukaram Gate fdr