

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		7		7		7			
8	Hyd	194	1044		6		6		6			
	Total	606	3055	0	14	0	14	0	14	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		3		3		3			
2	NLG	144	988		5		5		5			
3	MDK	107	933		2		2		2			
4	SDPT			2	5	2	5	2	5			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	15	2	15	2	15	0	0	
	Grand Total	1082	6468	2	29	2	29	2	29	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 12.07.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	SDP	Thunkibollaram	Vantimamidi	33KV	Gajwel	21.46	00.00	02.14		BD (Jumper cut)	Vantimamidi	-
2		Husnabad	Dharmaram	33KV	Husnabad	14.30	16.10	01.40		B/D heavy rain	Dharmaram	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 12.07.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Makthal	Satayasai	11KV	Narayanpet	14.25	15.15	00.50		Breakdown due to tree branch fallen on 11kv line sangapuram vlg	-
2		Makthal	Neredgama	11KV	Narayanpet	14.50	15.10	00.20		Breakdown due to unknown reason, rectified by itself	-
3		Manthangode	Kathwar	11KV	Narayanpet	00.10	05.55	05.45		Breakdown due to heavy rain and wind	-
1	NLG	Kethepally	Inupamula	11KV	Nalgonda	12.00	13.30	01.30	EL	Jumper cut	-
2		Kattangur	Bollepally	11KV	Nalgonda	07.00	08.00	01.00	EL	Insulator failed	-
3		Mellavai	Pasnoor	11KV	Devarakonda	15.00	16.10	01.10	EL	Conductor Snapped	-
4		Chinthapally	Rayanigudem	11KV	Devarakonda	12.10	13.45	01.35	EL	Pin insulator Failed	-
5		Choutuppal IPDS	Damera Agl	11KV	Choutuppal	12.11	14.18	02.07	EL	25kva DTR Failed near Muthiyamma Temple	-
1	MDK	Patancheru Town	Shanthinagar	11KV	Patancheru	07.25	08.15	00.50		B/D Due to Conductor Snapped	-
2		Patancheru Town	Town	11KV	Patancheru	21.05	22.10	01.05		BD Tree Branch Fallen the line	-
1	SDP	Mittapally	Mittapally	11KV	siddipet	10.30	11.20	00.50		B/D - Pin insulator fail, LC No. 19364	-
2		Dommeta	Surampally	11KV	Gajwel	18.50	19.40	00.50		11KV Line cut	-
3		Cherial	Cherial Town	11KV	Husnabad	16.40	17.20	00.40		Jumper Cut	-
4		Regulapally	Mallamcheruvu	11KV	Husnabad	15.30	17.45	02.15		Line Cut	-
5		GandiPally	GandiPally	11KV	Husnabad	15.15	20.30	05.15		Heavy rain fall	-
1	RR N	Medchal	Checkpost	11KV	Medchal	00.30	02.05	01.35	BD	11KV Disc Failed at Checkpost	-
1	RR E	IDA Uppal	Airtel	11KV	Habsiguda	07.30	09.20	01.50		11KV Airtel feeder lighting erector failed at SS Yard	-
2		St.No.08	Eggwood	11KV	Habsiguda	14.40	17.08	02.28		Tree branches fallen on 11kv line & Dog fallen on DTR & Jumper cut & HG Fuse failed at Veligutta Stadium Opposite	-
3		Uppal	Raghavendra Colony	11KV	Habsiguda	20.18	21.50	01.32		11KV Pin Insulator failed near Ganesh Temple at Raghavendra Colony	-
4		IDA Uppal	Ferrocast	11KV	Habsiguda	21.10	00.02	02.52		11KV Polymer Insulator failed at K.K Rao Company ,Tree fallen on 11KV line near Heritage Company & 11KV Jumper cut at CD Graviers	-
5		Aushapur	Aushapur	11KV	Keesara	21.30	22.10	00.40		Line patrolling but no visible fault	-
6		Narapally	Prathap Singaram	11KV	Keesara	21.40	22.55	01.15		Tree branches fallen on 11KV line at OU Colony	-
7		Aushapur	Aushapur	11KV	Keesara	22.50	00.10	01.20		11KV Disc failed at Jagath Swapna Ventura	-
1	HYD N	Macha Bollarum	Balaji Rice Mill	11KV	C-VI	20.11	21.28	01.17	EL,OL	AB Cable fault at Nalla Pochamme Temple	-
2		Macha Bollarum	Reddy Enclave	11KV	C-VI	21.24	23.30	02.06	EL	Pin Insulator flash over Sarayu Residency	-
3		Bhudevi Nagar	Yadamma Nagar	11KV	C-VI	21.40	23.58	02.18	EL	Tree branches fallen on lines at Telecom Colony & Disc Insulator flash over at Padmavathi Colony	-
1	HYD S	Kandikal Gate	Phool Bagh	11KV	III	20.07	22.34	02.27	EL	Arranged B/F on 11KV Saibaba Nagar feeder	-
1	HYD C	Asif Nagar	Military	11KV	VII	20.23	22.10	01.47	EL,OL	Tree branches fallen on line AB Switch at Military Area	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
2		Vittalwadi	Gandhi Kuteer	11KV	II	20.25	22.25	02.00	EL,OL-Rph	Tree branches fallen on lines at Airbus Apts	-