

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044									
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	4		4		4				
2	NLG	144	988		1		1		1			
3	MDK	107	933	1	2	1	2	1	2			
4	SDPT				4		4		3		1	11KV 1 No. Still
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	5	7	5	7	5	6	0	1	
	Grand Total	1082	6468	5	9	5	9	5	8	0	1	

TSSPDCL - LMRC / Corporate office

Date: 03.03.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Palkonda	Janampet	33KV	Mahabubnagar	09.45	14.13	04.28	O/L	Pole Broken Due to Lorry Accident & New Pole Erection at Pothulamadugu village	Janampet	No
2		Marikal	Kondapur	33KV	Narayanapet	08.20	11.05	02.45	E/L&O/L	33KV Jumper cut and Replaced	Kondapur	No
3		Nagarkurnool	Peddakothapally	33KV	Nagarkurnool	15.20	17.08	01.48	E/L	No Visabule Fault	Peddakothapally	No
4		Wanaparthy	Wanaparthy	33KV	Revally	18:50	19:20	0:30	E/L&O/L	Pin Binding fail near Appaipally	Wanaparthy	Alternate Supply Arranged form 33KV Peddakothapally Feeder
1	MDK	R.C.Puram	TS IIC	33KV	Patancheru	14:50	16:40	1:50		B/D Due to Insulator Failure	TS IIC	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	D Nagaram	Machireddypally	11KV	Suryapet	14:40	16:40	2:00	EL	Conductor snapped	No
1	MDK	EPIP-I	Chitrakoot	11KV	Sangareddy	14:35	15:10	0:35		Conductor Snapped	No
2		Anrich Bollaram	Sukaso	11KV	Patancheru	13.05	14.45	01.40		Conductor Snapped	No
1	SDPT	Peddakodur	Chinnakodur	11KV	Siddipet	11:15	12:00	0:45		B/D 11KV Line cut	No
2		THOTAPALLY	THOTAPALLY (R)	11KV	Husnabad	04.48	04.48	01.00		B/D DUE TO LINE CUT	No
3		Pamulaparthy ss	X press Feeder	11KV	Gajwel	13.00	14.25	01.25		11KV line cut	No
4		Mulugu SS	Bhahilampur.	11KV	Gajwel	15.30	Still			Jumper cut	No
1	RR N	Medchal	IDA-I	11KV	Medchal	15:35	16:15	0:40		11KV Pole damaged by DCM at REVL Company (Jumper Opened at REVL Company)	No
1	RR E	Street no 8	ISI	11KV	Habsiguda	11:34	12:42	1:08		11KV Line sanpped at Sridhar appt	No