

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1	3	1	3	1	3			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044									
	Total	606	3055	1	5	1	5	1	5	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		4		4		4			
3	MDK	107	933	1	1	1	1	1	1			
4	SDPT				5		5		5			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	11	1	11	1	11	0	0	
	Grand Total	1082	6468	2	16	2	16	2	16	0	0	

TSSPDCL - LMRC / Corporate office

Date: 24.03.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Zaheerabad	Mungi	33KV	Zaheerabad	13:10	15:00	1:50		Due to Roofing Sheet fallen on the line	Mungi	No
1	RR N	132KV Medchal	Keshavaram	33KV	Medchal	16:18	17:26	1:08		Tree fallen on the 33KV Line at Pudur Village	Keshavaram	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Maddur	Pediripad	11KV	Narayanapet	07.15	12.30	05.15		11KV Wire cut at Pediripad (V)	No
1	NLG	Kistapuram	Thammaram	11KV	Huzurnagar	3:25	7:30	4:05	E/L	11KV Line Snapped	No
2		Thungathurthy	Vempaty	11KV	Suryapet	05.20	08.00	02.40	E/L	11KV Conductor snapped	No
3		Bollepally	Jampally	11KV	Bhongir	08.05	10.05	02.00	E/L	11KV Line Snapped near Jampally (V)	No
4		Kolanpaka	Somaram	11KV	Bhongir	10.25	15.05	04.40	E/L	11KV Line Snapped near SS-13	No
1	MDK	Patancheru Town	Town	11KV	Patancheru	10:20	10:55	0:35		Bird fallen on the line	No
1	SDPT	CHILASAGAR	ANNASAGAR	11KV	Gajwel	18:10	18:55	0:45		11KV Line cut	No
2		DOULTHABAD	DOULTHABAD TOWN	11KV	Gajwel	17.57	18.32	00.35		HT/LT Line trip	No
3		DOMMATA	GAJULAPALLY	11KV	Gajwel	18.10	19.30	01.20		11KV Jumper cut	No
4		Mallaram	Sikindlapur	11KV	Siddipet	19.18	21.47	02.29		B/W 11 KV Line problem LC.No 17036	No
5		Peddachikode	Peddachikode	11KV	Siddipet	0:00	7:25	7:25		B/W for bat touch in the line LC.No 2802	No
1	RR N	Jeedimetla-Ss-III	Back let Hylam	11KV	Jeedimetla	18:05	19:05	1:00	EL	11KV AB Cable failure At Phase-V	No
2		Thurkapally	Thurkapally	11KV	Medchal	16.40	18.40	02.00		HT Line fallen on the LT Line at Mellakunta Cheruvu	No
3		Jagathgirigutta	Maqdoom Nagar	11KV	Medchal	07.00	07.40	00.40		11KV Cable End Kit failed at Maqdoom Nagar Common	No
1	RR E	Vayupuri	Vayupuri	11KV	Sainikpuri	8:40	9:32	0:52		Bird fallen on 11Kv line at Tharun Vihar Apport	No
2		Cherlapally-V	Pedda Cherlapally	11KV	Sainikpuri	17.38	18.58	01.20		Insulator failed double pole structure at near park	No