

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		4		4		4			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	6	0	6	0	6	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2	4	2	4	2	4			
2	NLG	144	988	1	2	1	2	1	2			
3	MDK	107	933	1		1		1				
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	4	6	4	6	4	6	0	0	
	Grand Total	1082	6468	4	12	4	12	4	12	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 01.05.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthi	Chinnamaroor	33KV	Wanaparthi	14.05	14.40	00.35	O/L	Plastic Cover fallen on the line and removed	Chinnamaroor	for Alternate supply Arranged from 33KV Velgonda
2		Wanaparthi	Solipur	33KV	Wanaparthi	19.05	22.20	03.15	O/L	tree follen on the line & insulator blosted at Chinnamandadi tanda	Solipur	-
1	NLG	Wadapally	YTPS	33KV	Miryalaguda	10.15	12.45	02.30	EL	Jumper cut at Pole No 234 near YTPS Plant	YTPS	-
1	MDK	Zaheerabad	Mungi	33KV	Zaheerabad	17.25	20.05	02.40		B/D Due to tree cutting	Mungi	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 01.05.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	MARIKAL	P.C.KUNTA	11KV	Narayanapet	07.00	07.55	00.55		Crow fallen on 11kv line at P.C.kunta vlg	-
2		KOSGI	CHENNARAM	11KV	Narayanapet	10.10	11.10	01.00		11kv line cut and fallen on channal at chennaram vlg	-
3		MOHAMMADABAD	MOHMMADABAD	11KV	Narayanapet	18.00	18.30	00.30		Cat fallen on DTR on Mohammadabad vlg	-
4		SALKARPET	PAGIDIYAL	11KV	Narayanapet	14.40	16.50	02.10		LT/HT at parugula thanda	-
1	NLG	Reddygudem	Reddygudem	11KV	Suryapet	06.00	09.30	03.30	EL	Insulator flashover	-
2		Junuthala	Pallepahad	11KV	Devarakonda	10.10	11.28	01.18	EL	11KV jumpercut	-
1	RR N	UMCC	Gajularamaram	11KV	Medchal	16.40	17.10	00.30	EL	Bird fallen on the 11KV Line at VT Garden	-
2		Bommarajpet	Karkalamma	11KV	Medchal	09.55	10.50	00.55	EL	11KV Jumper Cut & Replaced at Karkalamma	-
3		Keshavaram	Uddamarry	11KV	Medchal	13.05	14.49	01.44	EL/OL	Bird fallen on the 11KV Line at Uddamarry	-
4		Medchal	Navadurga	11KV	Medchal	17.50	19.18	01.28	EL	11KV Pin Insulator failed at IDA Medchal	-
1	RR E	Cherlapally-III	IOC	11KV	Sainikpuri	13.44	14.44	01.00		11Kv jumper cut at Dairy food and Quality food Company (L.Insp Arun)	-
1	HYD N	Zamistanpur	S.P College	11KV	V	11.31	13.10	01.39	EL,OL-Bph	Breaker fault at SS	Arranged B/F on 11KV Srinivasa Nagar Colony & 11KV P.R Nagar fdrs