

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		2		2		2			
	Total	606	3055	0	4	0	4	0	4	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	3	1	3	1	3			
2	NLG	144	988		4		4		4			
3	MDK	107	933	4		4		4				
4	SDPT				3		3		3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	5	10	5	10	5	10	0	0	
	Grand Total	1082	6468	5	14	5	14	5	14	0	0	

TSSPDCL - LMRC / Corporate office

Date: 22.05.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Amarchinta	Chandragattu Lift	33KV	Wanaparthy	23.00	06.05	07.05	E/L	Insulator failed, Tree fallen on the line	Chandragattu Lift	No
1	MDK	RC Puram	NSL	33KV	Patancheru	12:46	14:10	1:24		B/D Due to Jumper Cut	NSL	No
2		Gummadidala	AFA	33KV	Patancheru	15.30	17.30	02.00		B/D Due to Insulator Failure	AFA	No
3		Gummadidala	Dundigal	33KV	Patancheru	09.55	11.50	01.55		B/D Due to Jumper Cut	Dundigal	No
4		Gummadidala	GPSS-2	33KV	Patancheru	15.30	17.30	02.00		B/D Due to Insulator Failure	GPSS-2	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Thangadi	KUSMURTHY	11KV	Narayanpet	11.15	12.40	01.25		Disc failed at kusumurthy vlg	No
2		MADDUR	RERNIVETLA (PADRIPAD)	11KV	Narayanpet	07.25	10.34	03.09		Due to earthing fail at padripad vlg	No
3		MADDUR	DOREPALLY	11KV	Narayanpet	11.15	13.50	02.35		Crow fallen on 11kv line at dadaraopally vlg	No
1	NLG	AD Pally	Veerlapalem	11KV	Miryalaguda	6:00	6:45	0:45	EL	Tree branch fallen on line near Veerlapalem	No
2		Seethya Thanda	Seethya Thanda	11KV	Miryalaguda	08.15	10.09	01.54	EL	Insulator failed at Ganapativari gudem	No
3		Mukundapuram	Kalluru	11KV	Huzurnagar	02.05	07.30	05.25	EL	11KV Line snapped	No
4		Munagala	Barakathgudem	11KV	Huzurnagar	06.00	08.15	02.15	EL	11KV Line snapped	No
1	SDPT	Rampur	palamakula	11KV	Siddipet	2:30	3:30	1:00		Conductor snapped	No
2		Kammarlapally	Kothapally	11KV	Siddipet	01.40	18.15	16.35		B/D pole damage	No
3		RAIPOLE	RAIPOLE AGL	11KV	Gajwel	22.45	08.15	09.30		11KV Line snapped	No
1	RR E	Moula ali	Moula ali	11KV	Sainikpuri	16:50	18:00	1:10		Tree branches fallen on 11Kv line at SP Nagar	No
2		Chakripuram	Shilpa nagar	11KV	Keesara	17.00	19.25	02.25		Insulator failed	No
1	HYD S	Kandikal Gate	Neelam Centre	11KV	III	23.30	00.50	01.20	EL	Cable Fault at Saibaba Temple	Arranged B/F on 11KV Saibaba fdr
1	HYD C	Chilkaiguda	Parsigutta	11KV	II	13.32	14.50	01.18	EL-OL-Rph	Tree branches fallen on HT lines at Blue Moving Birds School	No