

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044		2		2		2			
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	3	1	3	1	3			
2	NLG	144	988	1	2	1	2	1	2			
3	MDK	107	933	1	2	1	2	1	2			
4	SDPT			3	1	3	1	3	1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	6	8	6	8	6	8	0	0	
	Grand Total	1082	6468	6	11	6	11	6	11	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 31.05.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Midjil	Vemula	33KV	Jadcherla	16.25	21.20	04.55	EL	2 Nos Insulator Replacement at Sangaye Pally	Vemula	-
1	NLG	Kangal	Thimannagudem	33KV	Nalgonda	15.50	18.20	02.30	E/L	2No.s 33Kv Insulators Failed	Thimannagudem	-
1	MDK	Jogipet	Wasar	33KV	Jogipet	13.45	18.40	04.55		BD due to Conductor snapped	Wasar	-
1	SDPT	Husnabad	Katkur	33KV	Husnabad	19.45	22.30	02.45		BD Heavy rain and wind	Katkur	Thotapally 33kv from 22:30
2		Mustyala	Chrial	33KV	Husnabad	19.50	22.40	02.50		BD Heavy rain and wind	Chrial	-
3		Siddipet	Narasapur	33KV	Siddipet	19.40	22.40	02.00		BD Heavy rain and wind	Narasapur	Peddakoduru from 22:40

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 31.05.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Manthangoud	KATHWAR	11KV	Narayanpet	09.20	09.30	00.10		Due to 11KV Line Phase to Phase at kathwar vlg	-
2		NARAYANPET	YADAGIRI ROAD	11KV	Narayanpet	17.10	18.50	01.40		Due to Insulator fail at nimra garden	-
3		MARIKAL	MADWAR	11KV	Narayanpet	17.50	18.12	00.22		Due to AB switch cut at madwar vlg	-
1	NLG	Doopahad	Lingala	11KV	Suryapet	05.50	07.30	01.40	E/L	11Kv Jumper cut	-
2		Marriguda	Vattipally	11KV	Devarakonda	09.10	10.16	01.06	E/L	B/D of 1-ph Dtr Probleam	-
1	MDK	Sadasivpet	Kambalapally	11KV	Sangareddy	18.46	20.11	01.25		B/D due to Tree branches fallen on the line	-
2		Patancheru Town	Town	11KV	Patancheru	20.35	22.40	02.05		B/D due to Tree branches fallen on the line	-
1	SDPT	Komuravelly	Kadavergu	11KV	Husnabad	19.25	21.45	02.20		Due to gale and wind	-
1	RR N	Madeenaguda	Widiao colony	11KV	Kukatpally	14.40	15.40	01.00	EL/OL	Tree fallin on the 11kv line at Allwyn colony	-
1	HYD N	Mothi Nagar	Ganesh Nagar	11KV	IV	07.42	09.12	01.30	All Indication	Jumper cut on 3rd Sectionalizer at Ganesh Nagar	-----
1	HYD S	Seetharambagh	Dhoolpet UG	11KV	IX	03.45	04.55	01.10	EL,OL	Cable fault	Arranged B/F on 11KV R.K.Pet fdr