

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1	4	1	4	1	4			
7	RR(E)	168	403		6		6		6			
8	Hyd	194	1044		2		2		2			
	Total	606	3055	1	12	1	12	1	12	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		2				
2	NLG	144	988	1	5	1	5	1	5			
3	MDK	107	933									
4	SDPT				5		5		5			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	3	10	3	10	3	10	0	0	
	Grand Total	1082	6468	4	22	4	22	4	22	0	0	

TSSPDCL - LMRC / Corporate office

Date: 19.07.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Kothur	Binju Sariya	33KV	Shadnagar	10.50	17.02	06.12	E/L	Conductor snapped at Thirupathi company	Binju Sariya	No
2		Kothur	Aryam Steel	33KV	Shadnagar	11.52	18.58	07.06	E/L	Conductor snapped at Aryam steel company & Jumper cut at 132KV SS	Aryam Steel	No
1	NLG	Kanagal	Pagidimarri	33KV	Nalgonda	15:05	17:20	2:15	E/L	33KV Disc & Insulator failed	Pagidimarri	No
1	RR N	132KV Malkaram	Shameerpet	33KV	Medchal	6:10	9:20	3:10		Peacock fallen on the 33KV line at near by BITS Campus	Shameerpet	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Narkatpally	Mandra	11KV	Nalgonda	7:00	9:45	2:45	E/L	11KV Jumper cut	No
2		Cherkupally	Cherkupally	11KV	Nalgonda	10.15	12.30	02.15	E/L	11KV Jumper cut	No
3		Pole center	Railway	11KV	Nalgonda	13.05	16.05	03.00	EL/OL	Loose line melting at Shivaram nagar	No
4		Mkundapuram	Express	11KV	Suryapet	02.40	06.30	03.50	E/L	11KV Conductor snapped	No
5		Choutuppal IPDS	Lakkaram	11KV	Choutuppal	14:49	16:12	1:23	EL/OL	11kv Insulator failed at Nomula Narsaiah petrol bunk near Lakkaram (V)	No
1	SDPT	Husnabad	Town-I	11KV	Husnabad	15:05	15:45	0:40		Lightening arrester failed	No
2		Begumpet	Madatha	11KV	Husnabad	15.30	15.45	00.15		Tripped on EL	No
3		Pandilla	Pandilla Rural	11KV	Husnabad	15.30	16.30	01.00		Insulator failed	No
4		Komuravelly	Posanpally	11KV	Husnabad	10.45	14.25	03.40		Tree fallen on the line	No
5		Bekkal	Kutigal	11KV	Husnabad	5:00	9:30	4:30		Insulator failed	No
1	RR N	DP Pally-II	Indofed	11KV	Jeedimetla	15:52	18:08	2:16		Tree fallen on the 11KV line at medchal Road	No
2		Athiwelly	Ravalkole Thanda	11KV	Medchal	17.45	19.40	01.55		Tree fallen on 11KV Line at Jayadharshini Backside	No
3		Gowdavelly	IDA Gowdawelly	11KV	Medchal	17.50	19.45	01.55		11KV UG Cable failed at Ajumer Biotech	No
4		Rajabollaram	Venkateswara Gutta	11KV	Medchal	17.30	19.50	02.20		Tree fallen on 11KV line at Water Plant, Rajabollaram	No
1	RR E	NGRI	Street no 8	11KV	Habsiguda	3:18	4:01	0:43		Tree branches on 11kv line at Street No 8 HBG	No
2		Cherlapally-IV	Devi Hitech	11KV	Sainikpuri	05.00	05.45	00.45		Tree branches fallen on the 11KV line at near Ushodaya Industry Phase-II	No
3		Balaji nagar	Sai baba	11KV	Keesara	16.36	17.36	01.00		Insulaotr fail at Market road	No
4		GKSR	HPCL	11KV	Keesara	15.10	15.55	00.45		Disc failed at HPCL Main road	No
5		GKSR	Yammunampet	11KV	Keesara	16.15	16.55	00.40		Disc failed at Srinidhi collage	No
6		GKSR	GKSR	11KV	Keesara	16:30	17:00	0:30		Disc failed at Ram reddy house	No
1	HYD N	Road No.22	Road No.22	11KV	X	13.32	14.36	01.04	EL,OL-Rph	Tree branches fallen on lines at Plot No.716	No
2		H.M.T	A.O.L	11KV	VI	23:15	0:20	1:05	EL,OL-Rph	No visible fault	Arranged B/F on 11KV Sri Sai Colony for