

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234	1	1	1	1	1	1			
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		6		6		6			
8	Hyd	194	1044		2		2		2			
	Total	606	3055	1	10	1	10	1	10	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	1	1	1	1	1			
2	NLG	144	988		3		3		3			
3	MDK	107	933	1		1		1				
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	4	2	4	2	4	0	0	
	Grand Total	1082	6468	3	14	3	14	3	14	0	0	

TSSPDCL - LMRC / Corporate office

Date: 04.05.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Alampur	Shanthinagar -1	33KV	Gadwal	14.28	18.36	04.08	EL	Pin binding replaced at Manapad X Road	Shanthinagar -1	No
1	MDK	Sadasivapet	Kondapur	33KV	Sangareddy	15:25	17:45	2:20		Jumper cut	Kondapur	No
1	RR S	Dharmasagar	Shabad	33KV	Ibrahibagh	14:30	16:20	1:50		Damaged Insulator Replaced at Nagarguda and tree branchaces removed near Shabad	Shabad	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Peddarevally	Chinnarevally	11KV	Jadcherla	16.10	17.50	01.40		Tree fallen on the line Pochamaguda Thanda	No
1	NLG	Dirsenspally	Miryala	11KV	Suryapet	10:40	12:30	1:50	EL	Insulator failed	No
2		Nadigudem	Nadigudem agl	11KV	Huzurnagar	07.15	10.15	03.00	EL	11KV Line snapped	No
3		Paladugu	Dathappagudem	11KV	Bhongiri	12.10	13.50	01.40	EL/OL	11KV Disc failed near Dathappagudem Village	No
1	RR S	Nanakramguda	Church	11KV	Gachibowli	3:25	4:40	1:15		Emaar HT Service Problem, 11KV Line AB Switch opened near Microsoft gate at Wipro.	No
1	RR N	Athiwelly	PHI	11KV	Medchal	13:20	14:55	1:35		Tree fallen on the 11KV line at PHI Company	No
1	RR E	Pocharam	Jodimetla	11KV	Keesara	16:40	17:22	0:42		Tree fallen on 11KV line at Jodimetla X road	No
2		Aushapur	Aushapur	11KV	Keesara	15.42	16.30	00.48		Tree fallen on 11KV line at Aushapur village	No
3		Aushapur	Madharam	11KV	Keesara	15.40	17.50	02.10		11KV line cut & 11KV jumper cut at Sai teja Vanchar	No
4		Narapallay	P.Singaram	11KV	Keesara	16.10	20.20	04.10		Tree fallen on 11KV line at Venkatadri town ship a, Balaji nagar & Pole Damaged	No
5		Singapur	RGK	11KV	Keesara	19.30	22.40	03.10		Tree fallen on 11KV T Royal Kutti appt	No
6		Singapur	Annojiguda	11KV	Keesara	18:20	19:35	1:15		Insulator failed at LIG Road	No
1	HYD N	Yellareddyguda	Shalivahana Nagar	11KV	X	19.40	20.55	01.15	EL,OL	HT Jumper cut at Keerthi Apts (6 amps charged at 20:16 Hrs)	No
1	HYD C	Lumbini Park	A.P Tourism	11KV	I	19.55	21.25	01.30	EL,OL-R&Bph	Cable fault	Partial feeder charged & Remaining arranged B/F on 11KV Galaxy Hotel feeder