

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		3		3		3			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		3		3		3			
	Total	606	3055	0	8	0	8	0	8	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2	1	2	1	2	1			
2	NLG	144	988		5		5		5			
3	MDK	107	933	1	2	1	2	1	2			
4	SDPT			1	3	1	3	1	3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	4	11	4	11	4	11	0	0	
	Grand Total	1082	6468	4	19	4	19	4	19	0	0	

TSSPDCL - LMRC / Corporate office

Date: 30.09.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	220/33KV SS Singotam	Wanaparthy	33KV	Nagarkurnool	14.00	17.32	03.32	E/L	33KV Jumper cut near Kodair malla vagu		NO
2		Kodair	Pebbair	33KV	Wanaparthy	20.15	21.15	01.00	E/L&O/L	Due to LA Blast		Alternate Supply Arranged From 33KV Chinnamaroor at 21:15
1	MDK	Gummadidala	Gummadidala	33KV	Patancheru	05.20	11.20	06.00		BD due to Tree fallen on the line		-
2	SDPT	Habsipur	Peddacheekodu	33KV	Siddipet	19.00	23.00	04.00		BD due to Insulator Failure		-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 30.09.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Dhanwada	Dhanwada	11KV	Narayanapet	06.00	08.35	02.35		Insulator failed at Dhanwada	-
1	NLG	Kudakuda	lylapuram	11KV	Suryapet	02.40	06.10	03.30	E/L	11Kv Insulator flashover	-
2		Mellacheruvu	Revoor	11KV	Huzurnagar	01.10	07.00	05.50	E/L	11Kv Line Snapped	-
3		Keethavarigudem	Velidanda	11KV	Huzurnagar	03.00	07.30	04.30	E/L	11Kv Junper Cut	-
4		Venkatapuram	Dathaipally	11KV	Bhongir	08.00	09.35	01.35	EL/OL	11kv Line snapped near Venkatapuram village	-
5		Venkatapuram	Venkatapuram	11KV	Bhongir	08.00	11.10	03.10	EL/OL	11kv Line snapped near Venkatapuram village	-
1	MDK	Patancheru Town	MIA-II	11KV	Patancheru	06.45	08.25	01.40		BD due to Conductor snapped	-
2		Bollaram - I	Town -I	11KV	Patancheru	19.23	21.40	02.17		BD due to Tree branch fallen on line	-
3	SDPT	Thornala	Thornala	11KV	Siddipet	07.00	08.50	01.50		B/D (Tree branches falen on the 11 KV Line)	-
4		GAJWEL PREGNAPUR SS	TOWN 2 FEEDER	11KV	Gajwel	19.35	20.58	01.23		TREE BRANCH FALL OVER 11 KV	-
5		GAJWEL PREGNAPUR SS	HOUSING BOARD FEEDER	11KV	Gajwel	20.10	21.00	00.50		RAIN PROBLEM	-
1	RR N	Rajabollaram	Rajabollaram	11KV	Medchal	09.00	10.09	01.09		Tree Branch fallen on the 11KV Line at Plastic Company, Rajabollaram	-
2		Dulapally	KK Society	11KV	Medchal	19.48	20.48	01.00		11KV Cable failed at Ahmad Galss Company	-
3		Devarayamjal	Pothaipally	11KV	Medchal	20.55	21.50	00.55		Tree fallen on the 11KV Line at Pothaipally	-
1	RR E	VP Nagar	RK Puram	11KV	Sainikpuri	20.53	21.55	01.02		11Kv Disk failure at Sri Colony and Lug cut at SS Yard (AE)	-
2		Sainikpuri	Vijayapuri	11KV	Sainikpuri	22.01	23.22	01.21		11Kv Disk failure at Sainikpuri	-
1	HYD N	Gunrock	Tirumalagiri	11KV	C-VI	20.00	21.35	01.35	All Indication	Pin Insulator falsh over at Biryani Darbar	-
2		Bhudevi Nagar	Yadamma Nagar	11KV	C-VI	19.55	23.00	03.05	EL,OL	2no Pin Insulator falsh over at Telecom Colony & Raja Laxami Apartment	(22:10 Hrs) Added partial loads on 111KV Gollaguda feeder
3		Hakimpet	Allenby Lines	11KV	C-VI	20.40	22.01	01.21	Auto Reclouser	Tree branches fallen on lines at Girls Court	-