

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	4	0	4	0	4	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	2	1	2	1	2			
2	NLG	144	988									
3	MDK	107	933		1		1		1			
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	5	1	5	1	5	0	0	
	Grand Total	1082	6468	1	9	1	9	1	9	0	0	

TSSPDCL - LMRC / Corporate office

Date: 22.02.2021

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Chinnamaroor	Kalwarala	33KV	Wanaparthi	12.28	13.02	00.34	E/L	Disk Fail near Chinnadagada	Kalwarala	Alternate Supply Arranged form 33KV SS Weepangandla

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 22.02.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	DAMARGIDDA	SAJNAPUR	11KV	Narayanapet	14.35	16.40	02.05		DUE TO 11KV LINE CUT, SAJNAPUR	-
2		GOTUR	PUSALPHAD	11KV	Narayanapet	11.40	12.19	00.39		DUE TO 11KV JUMPER CUT AND FALLEN ON LINE	-
1	MDK	EPIP-III	Tyechi Diecast Feeder	11KV	Sangareddy	19.15	19.55	00.40		BD Due to Tree Branch Fallen the line	-
1	SDP	BEJGAMA SS	LINGAREDDYPALLY FEEDER	11KV	Gajwel	13.10	14.20	01.10		11KV LINE CUT	-
2		PAMULAPARTHY SS	INDRANAGAR FEEDER	11KV	Gajwel	15.00	15.35	00.35		TREE BRANCH FALLEN	-
1	RR N	Thurkapally	Yadaram	11KV	Medchal	12.32	13.10	00.38		11KV Line Cut and replaced at Crusher Machine	-
2		Kistapur	Kistapur	11KV	Medchal	18.35	20.04	01.29		11KV Pole damaged by Tractor at Kistapur Road	-
1	RR E	Aushapur	Eduabad AGL	11KV	Keesara	07.00	10.50	03.50		HT/LT line Twisted at Eduabad Village	-
1	HYD N	New Bowenpally	Seethampuram	11KV	VI	18.40	19.45	01.05	EL,OL	Disc Insulator flash over & LT Line snapped at Arya Samaj	-