

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044		2		2		2			
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		2		2		2			
3	MDK	107	933									
4	SDPT				4		4		4			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	7	0	7	0	7	0	0	
	Grand Total	1082	6468	0	10	0	10	0	10	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 09.01.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Manthangoud	Kathwar	11KV	Narayanapet	11.45	12.15	00.30		insulator failure at bolapally village	-
1	NLG	B Chandupatla	Chandupatla	11KV	Suryapet	05.30	09.00	03.30	E/L	Insulator flashover	-
2		N B Gudem	Redlakunta	11KV	Huzurnagar	05.00	07.45	02.45	EL	11 KV LINE SNAPPED	-
1	SDP	MARPADGA	NAGIREDDYPALLI	11KV	GAJWEL	13.30	16.30	03.00		CONDUCTOR SNAPPED	-
2		Jakkapur	Shanigakunta	11KV	SIDDIPET	16.57	17.45	00.48		B/D - Bird fallen on the line	-
3		Laxmidvipally	Ibrahimpur	11KV	SIDDIPET	08.25	10.57	02.32		B/D - 11KV Jumer Cut, LC No. 11391	-
4		Chellapur	Chellapur	11KV	SIDDIPET	01.00	09.00	08.00		Insulator fail, 22270	-
1	RR N	UMCC	Crusher	11KV	Medchal	13.10	15.20	02.10		Breaker Mechanical Problem in SS and 11KV Pole damaged by Lorry and 11KV Pin Insulator failed and 11KV Line cut and replaced at MRCV Hotel	-
1	HYD S	Miralam	Hasan Nagar	11KV	III	23.30	01.00	01.30	EL,OL	Cable Fault	Arranged B/F on 11KV Madina Masjid fdr
1	HYD C	Golnaka	Sai Madhura Nagar	11KV	II	20.42	22.03	01.21	OL	Disc Insulator flash over at Petrol bunk near Dumping Yard	-