

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	1	85									
2	NLG	3	110									
3	MDK	6	81									
4	RR(S)	10	106		1		1		1			
5	RR(N)	45	274		1		1		1			
6	RR(E)	34	223									
7	Hyd	136	844		2		2		2			
	Total	235	1723	0	4	0	4	0	4	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	81	891									
2	NLG	109	738		6		6		6			
3	MDK	81	690		1		1		1			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	15	79									
	Total	325	2784	0	7	0	7	0	7	0	0	
	Grand Total	560	4507	0	11	0	11	0	11	0	0	

TSSPDCL - LMRC / Corporate office

Date: 23.08.2016

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	B Banda	NG Kothapally	11KV	Suryapet	10.40	13.00	02.20	E/L	Line melt	-
2		Mukundhapuram	Somaram	11KV	Huzurnagar	03.00	07.50	04.50	EL	Due to Jumper Cut at Somaram	-
3		Mukundhapuram	Munkudhapuram	11KV	Huzurnagar	13.10	14.34	01.24	EL	Due to Jumper Cut at Mukundhapuram	-
4		G.Yedavally	Narketpally IE	11KV	Nalgonda	02.40	07.35	04.55	E/L	Insulater failure	-
5		Nandanam	Nagireddypally	11KV	Bhongir	11.30	13.30	02.00	EL	Tree fallen On Line	-
6		Bollepally	Surepally	11KV	Bhongir	09.30	14.00	04.30	EL	11Kv Jumper snapped	-
1	MDK	Gummadidala	Mambapur	11KV	Medak	02.00	06.00	04.00		B/D Due to Tree fallen on 11KV Line at Mambapur village	-
1	RR S	Jalpally	Wadi-e-Mustafa	11KV	CHPT	06.15	07.15	01.00	OL	11KV Line cut at Mahamood Nagar	-
1	RR N	Vemana Colony	Suraksha Enclave	11KV	Kukatpally	17.39	18.58	01.19		11kv line PinInsulater Failure near Sai Deepthi Residency at Satya Enclave	-
1	HYD S	Panjasha	Metherwadi	11KV	III	16.25	19.20	02.55	EL,OL-Rph	Big tree fallen on line HT lines & Poles felldown	(2No DTR's Kept off at Hanuman Temple)
1	HYD C	Lake View	Kapadiya Lane	11KV	I	03.20	04.45	01.25	EL,OL-Bph	Cable fault	Arranged B/F on 11KV APSEBEA fdr