

TSSPDCL - LMRC / Corporate office

Date: 26.07.16

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Bibinagar	B.P.Pally	33KV	Bhongir	6:30	11:00	4:30	E/L	33KV Line Snapped at B.p.pally Village	B.P.Pally	At 07:00 hrs. alternative supply given from 132KV Choutuppal SS
1	RR S	Moinabad	Kethireddy Pally	33KV	Rajendranagar	17:00	18:30	1:30		33KV Insulator failed at Green Feel Farm House	Kethireddy Pally	No
1	RR N	Medchal	Devarayamjal	33KV	Medchal	17:04	19:20	2:16		33KV Disc failed at near by 33KV Kandlakoya SS	Devarayamjal	No
1	RR E	Bandlaguda	IDA Uppal	33KV	Habsiguda	7:21	10:30	3:09		End Kit Failed at PMR Gardens near Nagole	IDA Uppal	No
1	HYD N	132KV Gunrock	Hakimpet	33KV	Nehru Ngr	13.06	13.11	00.05	EL,OL	Cable punched at st anns jr college bollaram	Hakimpet	Loads transferred onto 33KV Gunrock - R.P.Nilayam line

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Mukundapuram	Somaram	11KV	Huzurnagar	11:00	14:00	3:00	E/L	11 kv line snapped at somaram village	No
2		Repala	Narsimhalagudem	11KV	Huzurnagar	4:00	8:00	4:00	E/L	11 kv line snapped at Repala village	No
3		Narsingbatla	Kooturugudem	11KV	Nalgonda	2:00	6:00	4:00	E/L	11KV Insulator Failure	No
4		Madgulapally	Kukkadam	11KV	Nalgonda	3:00	6:00	3:00	E/L	Insulator failed	No
5		B.Vellemla	Auravani	11KV	Nalgonda	3:00	6:00	3:00	E/L	11KV Insulator Failure	No
6		Rajapet	Singaram	11KV	Bhongir	7:00	9:00	2:00	E/L	11KV Line snapped at Singaram	No
7		Rajapet	Ranikunta	11KV	Bhongir	5:00	9:00	4:00	E/L	11KV Line snapped at Rajapet	No
8		Mothkur	Mothkur Rural	11KV	Bhongir	2:00	5:00	3:00	E/L	Jumper cut	No
9		Paladugu	Duppelly(narsapuram)	11KV	Bhongir	02.00	06.00	04.00	E/L	Jumper cut	No
10		Paladugu	Paladugu	11KV	Bhongir	23.00	02.00	03.00	E/L	11KV Diskfailed at Paladugu	No
11		Addagudur	Kotamarthy	11KV	Bhongir	02.00	06.00	04.00	E/L	11Kv Line snapped at Chirraguduur	No
12		Anathram	Hanumapur	11KV	Bhongir	7:00	9:15	2:15	E/L	11KV Line snapped near Hanmapur	No
1	MDK	Konapur	Raylapur	11KV	Toopran	5:30	10:00	4:30		11KV Insulator failed near Raylapur village	No
2		Chegunta	Vallure	11KV	Toopran	06.00	09.10	03.10		11KV Insulator failed near Vallure Lambadi thanda	No
3		Thogita	Aurangabad	11KV	Toopran	05.00	07.30	02.30		B/D Due to insulator failed	No
4		Gavulapally	Madoor	11KV	Toopran	05.00	08.20	03.20		B/D Due to 11KV Disk failed	No
5		Wadeepally	Wadepally	11KV	Medak	12:00	16:00	4:00		B/D Due to conductor snapped	No
1	RR S	NPA	Hasan Nagar	11KV	Rajendranagar	7:38	8:33	0:55	EL/OL	Tree branches fallen on 11kv Line at SS-1 T/F Hasan nagar	No
2		Kattedan-I	Feeder-I	11KV	Rajendranagar	13.40	15.10	01.30	EL/OL	11KV Line snapped at Electro flow battery company due to CTBT Problem	No
3		Gaganpahad	Shivashakti	11KV	Rajendranagar	07.39	08.49	01.10	E/L	11KV Line AB switch insulator failed at Shivashakti Bakery	No
4		Rajendranagar	Jalababa nagar	11KV	Rajendranagar	09.55	11.57	02.02	EL/OL	11KV AB cable failed at Dairy Farm	No
5		Leninnagar	Almasguda	11KV	Champapet	15.40	16.45	01.05	OL	No visible fault found	No
6		Rangampally	Roopkhanpet	11KV	Vikarabad	15:58	19:30	3:32		11KV disc failed at Lakhnapur village outside	No
1	RR N	Ayyappa Society	MyHome	11KV	Gachibowli	16:15	18:55	2:40		11kv line pin-insulator failed at Ashoka Hotel, Ayyappa Society	No
2		Gachibowli	Gopanpally	11KV	Gachibowli	11.50	13.10	01.20		11kv line pin-insulator failed at Global School, Gopanpally	No
3		Kaithalapur	IDAL	11KV	Gachibowli	17.50	19.05	01.15		11kv line AB-Switch Sparked at IDAL Cheruvu	No
4		Jeedimetla-IV	AAI matha	11KV	Kukatpally	08.25	09.55	01.30		11kv line pin Insulater failure at AAI matha Temple	No
5		Hudatruckpark	Sri sai nagar	11KV	Kukatpally	11.44	12.44	01.00		11kv line pin Insulater failure at Sri sai nagar	No
6		Vemana Colony	Suraksha Enclave	11KV	Kukatpally	15.36	16.55	01.19		11kv line Disk failure near Godhavari Apt,Suraksha Enclave	No
7		Jagathgirigutta	Shiridi Hills	11KV	Medchal	06.15	07.40	01.25		11KV Cable Kit Failed at Thumma Chettu T/F, RGK Colony	No
8		Kompally	Petbasheerbad	11KV	Medchal	07.12	08.05	00.53		Tree Fallen on 11KV Line at Panchaseela Colony, Petbasheerbad	No
9		Medicity	Munirabad	11KV	Medchal	07.45	10.15	02.30		11KV Pin Insulator Failed at Munirabad Village	No
10		Subash Nagar	Pragatools	11KV	Medchal	17.30	18.15	00.45		11KV Pin Insulator Failed at Beerappa T/F, Jeedimetla	No

11		Devarayamjal	Mandaipally	11KV	Medchal	19.20	20.40	01.20		11KV Pin Insulator Failed at Sriknth Reddy Bavi,Mandaipally	No
12		Shameerpet	Alankritha	11KV	Medchal	19.00	21.00	02.00		Tree Fallen on 11KV Line at Dongalamaisamma	No
13		UMCC	RM Nagar	11KV	Medchal	20.35	21.35	01.00		11KV Pin Insulator Failed at Ushodaya colony Phase-II	No
14		HMT	Quthubullapur	11KV	Medchal	16:45	18:15	1:30		Tree Fallen on 11KV Line at HMT Company	No
1	RR E	Polytechnic	Srinivasapuram	11KV	Habsiguda	6:43	7:43	1:00		Tree branches fallen on 11KV line at Srinivasa Puram	No
1	HYD N	Bora Banda	Pilli Darga	11KV	IV	06.32	08.30	01.58	EL	Cable fault at SBI, Bora Banda	No
2		H.P.S.	Suryodaya Complex	11KV	IV	6:40	8:05	1:25	All Indication	No Visible Fault due to heavy Rain	No
3		H.P.S.	Begumpet Nala	11KV	IV	7:00	8:10	1:10	EL,OL-Rph	No Visible Fault due to heavy Rain	No
4		Kundanbagh	Methodist Colony	11KV	IV	6:45	8:12	1:27	EL	No Visible Fault due to heavy Rain	No
5		Mothi Nagar	B.S.Puri	11KV	IV	19:16	20:30	1:14	EL,OL-Rph	Insulator flash over at B.S.Puri Clny	No
6		Begumpet	Shanthei Bagh	11KV	IV	19:35	20:35	1:00	OL-R&Bph	AB Switch sparking at Shanthei Bagh Appt	No
7		Chilalguda	New Boiguda	11KV	V	6:30	8:45	2:15	EL	No Visible Fault due to heavy Rain	No
8		Clock Tower	Anjali	11KV	V	7:22	8:30	1:08	EL	No Visible Fault due to heavy Rain	No
9		Clock Tower	Station Road	11KV	V	7:10	9:00	1:50	EL	Tree branches touching to Lines at St. Frances Jr. College	No
10		Airport	Prakash Nagar	11KV	IV	8:30	9:50	1:20	EL	Pin Insulator flash over at MIG B-64	No
11		Patigadda	Rani Gunj	11KV	V	6:40	9:10	2:30	EL	No Visible Fault due to heavy Rain	No
12		Clock Tower	Rezimental Bazar	11KV	V	8:26	9:30	1:04	EL	Faulty DTR at Opp. Darga	No
13		H.M.T	Sri Sai Colony	11KV	VI	16:40	19:00	2:20	EL	CT meter blast at Chintal Main Road	No
14		H.M.T	A.O.L	11KV	VI	16:55	18:40	1:45	EL	No Visible Fault	No
15		Road No.12	Kanka Durga	11KV	X	6:25	7:30	1:05	EL	No Visible Fault due to heavy Rain	No
16		Srinagar Colony	Srinagar Colony	11KV	X	7:35	8:45	1:10	OL-Rph	Disc Insulator flash over at Srinagar Colony	No
17		N.I.M.S.	Andhra Jyothi	11KV	X	8:20	10:30	2:10	OL-Bph	Tree branches touching to Lines at Road No.5	No
18		Madhapur	APIIC-II	11KV	X	11:30	12:30	1:00	EL	Bamboo Stick fallen on lines at Madhapur	No
19		Yousufugda	Hylam Colony	11KV	X	17:02	18:40	1:38	EL	No Visible fault	No
20		Madhapur	Shilparammam	11KV	X	22.58	02.15	03.17	EL,OL-Rph	No Visible fault	No
1	HYD S	Miralam	Tadbund	11KV	III	07.02	08.45	01.43	EL,OL-Rph	HT Line snapped at Tadbund X Road	No
2		Petlaburz	Chowk	11KV	III	16:25	17:40	1:15	EL,OL-Rph	Insulator flash over Chowk	No
3		Koti Womens College	Ganesh Temple	11KV	IX	8:06	9:22	1:16	EL	No Visible Fault	No
1	HYD C	Nizam College	Shantha Bai Nursing Home	11KV	I	06.17	08.22	02.05	EL,OL-Rph	Faulty 11KV Fathe Maidan feeder loads	No
2		Indira Park	Kavadiguda	11KV	I	07.11	08.40	01.29	EL	Faulty DTR at Kavadiguda	No
3		N.I.M.S.	Erramanzil	11KV	I	10.10	12.10	02.00	All Indication	Faulty 3Way RMU at I.C.Quarters	No
4		Gudimalkapur	Zeba Bagh	11KV	VII	07.11	09.11	02.00	EL	Tree branches touching to Lines at Lines at Gayatri Complex	No
5		S.D.Hospital	Police Mess	11KV	VII	7:53	10:13	2:20	EL	Pin Insulator flash over at Tulsi School	No
6		Nampally	Pearls Regency	11KV	VII	18.57	20.14	01.17	W/O Indication	No Visible fault	Arranged B/F on 11KV Fapci & Red Hills fdrs

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	1	85									
2	NLG	3	110									
3	MDK	6	81									
4	RR(S)	10	102	1	5	1	5	1	5			
5	RR(N)	45	271	1	14	1	14	1	14			
6	RR(E)	33	203	1	1	1	1	1	1			
7	Hyd	135	837	1	29	1	29	1	29			
	Total	233	1689	4	49	4	49	4	49	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	78	891									
2	NLG	109	738	1	12	1	12	1	12			
3	MDK	79	690		5		5		5			
4	RR(S)	31	341		1		1		1			
5	RR(N)	8	48									
6	RR(E)	15	78									
	Total	320	2786	1	18	1	18	1	18	0	0	
	Grand Total	553	4475	5	67	5	67	5	67	0	0	