

TSSPDCL - LMRC / Corporate office

Date: 04.07.2016

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Siddipet	Peddakodur	33KV	Siddipet	19.05	21.05	02.00		B/D due to Tree fallen on line		-
2		Thukkapur	Thukkapur	33KV	Siddipet	18.45	19.45	01.00		B/D due to Conductor snapped near DTR		-
3		Narsapur	Narsapur	33KV	Medak	15.05	16.20	01.15		B/D due to Conductor snapped		-

TSSPDCL - LMRC / Corporate office

Date: 04.07.2016

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	TELKAPALLY	GOUREDDYPALLY	11KV	Nagarkurnool	14.30	17.15	02.45		11KV WIRE CUT NEAR TELKAPALLY	-
1	NLG	Padamatpally	Thuruppally	11KV	Devarakonda	10.00	11.00	01.00	EL	Jumper Cut	-
2		Tirumalagiri	Thatipamula	11KV	Suryapet	10.15	13.00	02.45	EL	11 KV Line cut near T.Giri Town	-
3		Gaddipally	Medaram	11KV	Huzurnagar	07.30	10.00	02.30	EI	Due To 11 kv Insulator failure	-
4		P.D.Pally	P.D.Pally	11KV	Nalgonda	11.30	12.15	00.45	E/L	Tree branch fallen on line	-
5		Velugupally	Ithavarigudem	11KV	Nalgonda	09.00	13.45	04.45	E/L	11KV insulator fairled at SS-21	-
6		Mushampally	Erugantipally	11KV	Nalgonda	02.00	06.00	04.00	E/L	Tree branch fallen on line at SS-1	-
7		Nemmani	Merlakunta	11KV	Nalgonda	06.00	10.30	04.30	E/L	Gross patti cut and snapped to cross arm at Thondlai	-
8		Narkatpally IE	Goplaipally	11KV	Nalgonda	08.45	12.00	03.15	E/L	11KV line cut at near SS	-
9		B.Vellemla	B.Vellemla AGL	11KV	Nalgonda	12.30	13.30	01.00	E/L	Spiral died on 11KV line at Kondapakonigudem	-
10		B.Vellemla	B.Vellemla Town	11KV	Nalgonda	12.30	13.30	01.00	E/L	11KV jumper cut	-
1	RR S	NPA	Shastripuram	11KV	RJNR	12.20	13.07	00.47		No Fault	-
2		Puppalguda	Puppalguda	11KV	RJNR	16.10	17.10	01.00		Bird Fallen On 11 KV Line at Durganagar Colony	-
3		Ibrahembagh	Military I	11KV	RJNR	09.20	10.18	00.58		Iranrod fallen on 11 KV Line at Manchirevulu	-
4		Jalpally	Jalpally	11KV	CHPET	13.15	14.55	01.40	EL	Copper patti touched to AB switch Handle pipe at Jalpally (V)	-
1	HYD N	Mothi Nagar	P.R Nagar	NT	IV	06.56	08.37	01.41	EL	No Visible Fault	-

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	1	85									
2	NLG	3	110									
3	MDK	6	81									
4	RR(S)	10	95		4		4		4			
5	RR(N)	45	249									
6	RR(E)	33	203									
7	Hyd	135	832		1		1		1			
	Total	233	1655	0	5	0	5	0	5	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	78	891		1		1		1			
2	NLG	109	738		10		10		10			
3	MDK	75	683	3		3		3				
4	RR(S)	30	335									
5	RR(N)	8	48									
6	RR(E)	15	78									
	Total	315	2773	3	11	3	11	3	11	0	0	
	Grand Total	548	4428	3	16	3	16	3	16	0	0	