

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	38	209		3		3		3			
5	RR(N)	77	399	1	6	1	6	1	6			
6	RR(E)	38	347		3		3		3			
7	Hyd	183	982		4		4		4			
	Total	494	2884	1	16	1	16	1	16	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	106	969	2	2	2	2	2	2			
2	NLG	150	948	2	10	2	10	2	10			
3	MDK	87	828	6		6		6				
4	RR(S)	27	316									
5	RR(N)	8	48									
6	RR(E)	18	80									
	Total	396	3189	10	12	10	12	10	12	0	0	
	Grand Total	890	6073	11	28	11	28	11	28	0	0	

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Nagarkurnool	Bijinapally	33KV	Nagarkurnool	17.28	21.15	03.47	E/L	33Kv Line Cut near at Vatttem village	Bijinapally	Jumpers Opening of Vatttem at 18:18 Hrs and Bijinapally supply Ok Vatttem Feeder supply Dark
2		Nagarkurnool	Telkapally	33KV	Nagarkurnool	18.01	21.30	03.29	E/L	Insulator Damaged and Pin Insulator Replasmnt at Jamistapur Gate	Telkapally	-
1	NLG	Bibinagar	Bhongir	33KV	Bhongir	17.07	18.33	01.26	E/L	Tree Fallen On Line Near Saiconvintional Function Hall	Nandanam, Chandupatla	-
2		132KVSS Haliya	Rajavaram	33KV	Miryalguda	15.30	16.00	00.30	E/L	33KV Nayakunithanda lift feeder jumpers Opened near Nellikal sub-station tapping, due to the lift feeder disc insulator failed.	Rajavaram, Pottichelma, and Nellikal	Supply restored
1	MDK	Siddipet	Raghavapoor	33KV	Siddipet	15.35	18.10	02.35		B/D Due to Jumper cut	Raghavapoor	-
2		Gajwel	Mulugu	33KV	Tooran	14.30	21.15	06.45		B/D Due to tree fallen on the line	Mulugu	-
3		Shenigaram	Bejjenki	33KV	Siddipet	16.35	18.25	01.50		B/D Due to tree fallen on the line	Bejjenki	-
4		Shenigaram	Ramachandarpur	33KV	Siddipet	14.25	18.30	04.05		B/D Due to pin Insulator failure	Ramachandarpur	-
5		Shenigaram	Shenigaram	33KV	Siddipet	14.40	18.35	03.55		B/D Due to Jumper Cut	Shenigaram	-
6		Sadasivpet	Koheer	33KV	Sangareddy	22.05	10.05	12.00		B/D Due to Jumper cut and CT blast	Koheer	-
1	RR N	Medchal	33KV Keshavaram	33KV	Medchal	18.35	20.40	02.05	BD	CT Line Isolator B Phase Jumper cut & CT Oil Replaced in SS	33KV Keshavaram	-

TSSPDCL - LMRC / Corporate office

Date: 05.04.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Parpally	Achrayapur	11KV	Mahabubnagar	17.30	19.20	01.50		11KV Insulator Damage at Veerannapally (V)	-
2		Kourampet	Kourampet Town	11KV	Jadcherla	15.40	17.45	02.05		HT/LT Near New Bus Stand And Tree Follen On The 11KV Line Near Kourampet	-
1	NLG	Mattampally	Allipuram	11KV	Huzurnagar	12.00	15.00	03.00	E/L	11 kv line snapped at Allipuram (V)	-
2		Narketpally	Mandra	11KV	Nalgonda	06.30	08.30	02.00	E/L	Lighting Arroster failure	-
3		Narayanpur	K.K.Gudem	11KV	Nalgonda	15.30	16.40	01.10	E/L	11KV line cut SS.21	-
4		Anathram	Anathram	11KV	Bhongir	07.00	09.20	02.20	E/L	Mother DTR Failure at Anatharam	-
5		Raghunthapur	Challur	11KV	Bhongir	15.30	17.30	02.00	E/L	Tree Fallen On Line Near Raghunathpur	-
6		Nemaragomula	Jamilapet	11KV	Bhongir	16.00	19.30	03.30	E/L	11KV Line snapped at Mahadevpur Village	-
7		Rajapet	Renikunta	11KV	Bhongir	02.00	05.00	03.00	E/L	11KV Line snapped at B egampet	-
8		NG Bandal	Konapur	11KV	Bhongir	15.10	18.10	03.00	E/L	11KV Jumper snapped at Konapur	-
9		M.T.Pally	Mulkalapally	11KV	Bhongir	15.45	19.45	04.00	E/L	11KV Jumper Cut at Mulakapally	-
10		Bhongir SS	Urabancolny	11KV	Bhongir	18.00	19.20	01.20	E/L	11KV Line Snapped at Nalgonda Road	-
1	RR S	Ibrahimbagh	Military-I	11KV	RJNR	16.13	17.38	01.25	B/D	Tree branches fallen on 11KV Line at Ibrahimbagh	-
2		Mamidipally	Pahadishareef	11KV	CPT	15.45	16.45	01.00	EL/OL	Copper patti cut at Dargah DTR	-
3		Leninnagar	Badang pet	11KV	CPT	06.20	07.24	01.04	EL	Breaker relay problem	-
1	RR N	KPHB	Adithyanagar	11KV	Kukatpally	00.14	01.58	01.44	BD	Tree fallen on the 11kv Line at Pragathi nagar Road	-
2		J D M SS-III	FOX Sagar	11KV	Kukatpally	03.30	04.30	01.00	BD	11kv AB Cable Failure at Phase-V	-
3		J D M SS-III	Vinayaka nagar	11KV	Kukatpally	12.00	14.00	02.00	BD	11kv AB Cable Failure at V S S Engineering Company	-
4		Mayurinagar	Laxmi Nagar	11KV	Kukatpally	17.00	17.30	00.30	BD	Tree fallen on the 11kv Line at Petrol Pump Miyapur	-
5		Medchal	IDA Kistapur	11KV	Medchal	05.40	06.50	01.10	BD	Tree Fallen on 11KV Line at Kistapur Road	-
6		Kistapur	Goshaiguda	11KV	Medchal	02.20	04.10	01.50	BD	Tree Fallen on 11KV Line at Kistapur Village	-
1	RR E	Mohan Nagar	R.K Puram	11KV	SRNR	16.58	17.46	00.48		HT/LT Line Touching at Telepone Colony	-
2		Bhagathsing Nagar	Shivapuri	11KV	SRNR	15.44	16.30	00.46		Cocount Tree Branches fallen on 11KV line at Bank Colony	-
3		Hayath Nagar	Kalavancha	11KV	SRNR	16.40	19.00	02.20		DTR Copper Peeti cut at Baga Laxmi Rice Mall	-
1	LVD N	Prashasan Nagar	Journalist Colony	11KV	X	02.24	04.13	01.49	EL,OL	Tree branches fallen on Lines at Journalist Colony	-----
2		Film Nagar	Ambedkar Nagar	11KV	X	09.54	11.40	01.46	OL-Bph	Tree fallen on 1st Pole at Film Nagar	-----

3	TTD N	Osm. University	Mettuguda	11KV	V	14.45	01.35	10.50	EL	Cable fault	At 15.20 hrs Partial 25% feeder charged stood OK
1	HYD S	C.R.P.F	C.R.P.F	11KV	III	16.50	18.35	01.45	EL,OL-Bph	Tree fallen on lines at CRPF Gate.No.2	-----