

TSSPDCL - LMRC / Corporate office

Date: 11.03.17

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Maddur	Vepoor	33KV	Mahabubnagar	15.10	16.35	01.25	E/L	Tree fallen on the line	Vepoor	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Jadcherla	Burgupally	11KV	Jadcherla	08.00	11.50	03.50		11KV Wire cut near Allore	No
2		Shadnagar	Kishannagar	11KV	Jadcherla	12.15	15.50	03.35		11KV Wire cut at yard	No
3		Shadnagar	Nagulpally	11KV	Jadcherla	14.15	15.35	01.20		Phase to phase near Pargi road	No
1	NLG	Cheruvupally	Cheruvupally	11KV	Nalgonda	9:45	12:00	2:15	E/L	11KV Insulator failed	No
2		Sharajipet	Sharajipet	11KV	Bhongir	07.00	09.40	02.40	EL	Jumper cut	No
3		Kopple	Bollaram	11KV	Devarakonda	09.00	12.00	03.00	EL	Jumper cut	No
4		Durajpally	Vallabhapuram	11KV	Suryapet	11.20	14.00	02.40	O/L	Jumper cut	No
1	RR S	Puppalaguda	Manikonda	11KV	Rajendranagar	15:50	17:30	1:40		No visible fault	No
2		Peddemulu	Indole	11KV	Vikarabad	04.50	07.00	02.10	EL/OL	11KV Disc failed	No
1	RR N	Ayyappa Society	Hyundai	11KV	Gachibowli	2:12	4:20	2:08		11kv Pole fallen due to digging near Crusher at Thanda, Ayyappa Society(Gurukul Trust)	No
2		Borabanda	Gayathri Nagar	11KV	Gachibowli	01.30	03.30	02.00		11kv Cable end-kit failed at Chettakundi T/F(Dustbin T/F) , Vivekananda Nagar.	No
3		vijayanagar	AS Raju nagar	11KV	Kukatpally	16.40	17.40	01.00		T/F Brass patti cut touched channel at H P Gas Office Ennadu colony	No
4		Madinaguda	Miyapur	11KV	Kukatpally	16.43	17.13	00.30		Net wire fallen on the 11kv Line at Balaji Redence Miyapur	No
5		J D M -SSIII	Vinayakanagar	11KV	Kukatpally	18.30	20.00	01.30		11kv AB Cable failure at M N S Plastic vinayakanagar	No
6		Kompally	NCL	11KV	Medchal	13.15	14.40	01.25		11KV UG Cable Failed at Shivashivani School	No
7		Subash Nagar	Jeedimetla	11KV	Medchal	12:50	13:45	0:55		11KV Pole damaged by Car at Venkateshwara Garden, NCL	No
1	RR E	Maruti Nagar	More	11KV	Saroonagar	5:20	7:35	2:15		11kv Line snapped at near Bata showroom Margadarshi Colony	No
2		Taramatipet	Bandaravirala	11KV	Saroonagar	06.00	14.35	08.35		Tree fallen on 11kv line and 9 Nos 11kv Ploe damaged at Sadupally Village	No
3		Fruit Market	Hanuman nagar	11KV	Saroonagar	06.12	07.00	00.48		Cocount tree branches fallen on 11kv Line at Vikashnagar Café	No
1	HYD N	LV Prasad Marg	LV Prasad Film Lab	11KV	Jublee Hills	07.16	10.00	02.44	EL	Breaker problem at SS	Arranged partial B/F on 11KV B.S.N.L fdr, at 11:15 hrs Remaining fdr B/F on 11KV Cinee Max fdr

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	153									
2	NLG	18	406									
3	MDK	85	383									
4	RR(S)	38	237		2		2		2			
5	RR(N)	77	398		7		7		7			
6	RR(E)	38	347		3		3		3			
7	Hyd	169	966		1		1		1			
	Total	473	2890	0	13	0	13	0	13	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	104	894	1	3	1	3	1	3			
2	NLG	150	728		4		4		4			
3	MDK	94	826									
4	RR(S)	31	289									
5	RR(N)	8	49									
6	RR(E)	18	79									
	Total	405	2865	1	7	1	7	1	7	0	0	
	Grand Total	878	5755	1	20	1	20	1	20	0	0	