

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		8		8		8			
	Total	606	3055	0	12	0	12	0	12	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	3	3	1	3	1	3			2 Nos. 33KV Still
2	NLG	144	988	1	16	1	16	1	16			
3	MDK	107	933	1	1	1	1	1	1			
4	SDPT				7		1		1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	5	27	3	21	3	21	0	0	
	Grand Total	1082	6468	5	39	3	33	3	33	0	0	

TSSPDCL - LMRC / Corporate office

Date: 01.08.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Maddur	Vepoor	33KV	Narayanpet	21.40	Still		EL		Vepoor	-
2		Sri Rangapur	Scan Energy	33KV	Shadnagar	17.45	22.57	05.12	EL	No Visible fault due to Rain	Scan Energy	-
3		Gadwal	Alwalpad	33KV	Gadwal	22.30	Still		EL		Alwalpad	-
1	NLG	Ramapuram	Thogarrai	33KV	Huzurnagar	04.00	09.30	05.30	E/L	33KV DISK Failed	Thogarrai	-
1	MDK	Zaheerabad	Machnoor	33KV	Zaheerabad	13.20	14.50	01.30		BD Due to insulator Fail	Machnoor	-

TSSPDCL - LMRC / Corporate office

Date: 01.08.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	K V Pet	Bandameedipally	11KV	Jadcherla	23.50	07.50	08.00		HT/LT Near Polepally(Vi) Area.	-
2		Nawabpet	Kondapur	11KV	Jadcherla	12.48	14.30	01.42		11Kv Insulator Failure Near Kondapur(Vi).	-
3		Karvena	Karvena	11KV	Jadcherla	13.23	15.22	01.59		.11Kv jumper Cut Near Karvena(Vi)	-
1	NLG	Athmakur(S)	Athmakur	11KV	Suryapeta	05.10	08.15	03.05	E/L	Line Snapped	-
2		Koduru	Koduru	11KV	Suryapeta	05.45	07.30	01.45	E/L	Insulator flashover	-
3		Dirincherla	Chellepally	11KV	Huzurnagar	06.00	08.50	02.50	EL	11 KV Inslater failed	-
4		Gondiryala	Chimiryala	11KV	Huzurnagar	03.00	04.50	01.50	EL	11 KV Line snapped	-
5		Ponugodu	Ponugodu	11KV	Huzurnagar	13.30	16.00	02.30	EL	11 KV Line snapped	-
6		Donipamula	Nermata	11KV	Nalgonda	11.40	14.30	02.50	EL	11KV Line Jumper Cut	-
7		Aitipamula	Rasoolgudem	11KV	Nalgonda	13.30	16.30	03.00	EL	HT/LT Line Milting	-
8		Edulur	Garlabaigudam	11KV	Nalgonda	10.15	13.00	02.45	EL	Insulator failed	-
9		Thoragal	Thangalavari gudam	11KV	Nalgonda	15.10	17.00	01.50	EL	11KV Line Jumper Cut	-
10		P.D.Pally	Gundlapally	11KV	Nalgonda	08.00	10.30	02.30	EL	11 Kv line cut	-
11		P.D.Pally	Kanchanapally	11KV	Nalgonda	10.00	12.10	02.10	EL	Tree fallen on line	-
12		Devarakonda	K.B.Pally	11KV	Devarakonda	14.55	15.55	01.00	EL	11KV Line Jumper Cut	-
13		Nemaragomula	Nemaragomula	11KV	Bhongir	05.00	08.00	03.00	EL/OL	11kv Disc Failed & 11kv Line Snapped near Kondamadugu Village	-
14		Datherpally	Jangampally	11KV	Bhongir	06.00	07.00	01.00	EL	11 kv Line Snapped at Rallajangam thanda	-
15		Mothkur	Areygudem	11KV	Bhongir	04.00	08.30	04.30	EL	11 kv Line Snapped at SS-2 Near Areygudem Village	-
16		Jangam	Vacyathanda	11KV	Choutuppal	08.00	10.00	02.00	EL/OL	11kv Insulator Failed & 11kv Jamper Sanpped near Jangam Village	-
1	MDK	Gaddapotharam -II	Khajipally Indl.	11KV	Patancheru	04.20	09.35	05.15		BD due to disk fail	-
1	SDP	Husnabad	Pandilla	11KV	Husnabad	09.50	15.20	05.30		Insulator failure same rectified	-
2		Pandilla	Pandilla Rural	11KV	Husnabad	22.00	Still			BD	-
3		Pandilla	Potlapally	11KV	Husnabad	22.00	Still			BD	-
4		Gandipally	Gandipally	11KV	Husnabad	19.20	Still			BD	-
5		Gouravelly	Gudatipally	11KV	Husnabad	19.45	Still			BD	-
6		Bejjanki	Regulapally	11KV	Husnabad	19.15	Still			BD	-
7		Gurjakunta	Gurjakunta 24 Hrs	11KV	Husnabad	08.05	Still			BD	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR S	Kaithalapur	Kaithalapur	11KV	Kondapur	16.31	18.10	01.39	BD	11kv Polymar disk failed near Kaithalapur	-
1	RR N	Jagathgirigutta	IDA	11KV	Medchal	16.20	17.00	00.40		11KV Pin Insulator failed at Devamma Basti	-
1	RR E	Aushapur	NFC nagar	11KV	Keesara	10.15	11.45	01.30		Disk fail at Gas office back side	-
2		Singapr	RGK	11KV	Keesara	15.20	18.20	03.00		Tree fallen on 11kv line at RGK back side	-
1	HYD N	Bhudevi Nagar	Ram Raj Nagar	11KV	VI	14.05	16.05	02.00	EL,OL	Pin Insulator flash over at Swarna Dhama Nagar	-
2		Bansilalpet	Botany School	11KV	V	23.45	00.49	01.04	All Indication	Arranged B/F on 11KV Gas Mandi fdr	-
1	HYD S	Malakpet	Municipal Colony	11KV	VIII	00.40	02.46	02.06	EL	Breaker problem at SS	Arranged B/F on 11KV Shakar Ngr fdr
2		Panjasha	Sultan Shai	11KV	III	23.00	01.00	02.00	All Indication	Pin Insulator flash over at Sultan Shai	-
1	HYD C	Fever Hospital	Fever Hospital	11KV	II	01.05	03.15	02.10	EL,OL-Rph	No Visible Fault	-
2		Fever Hospital	Tourist Hotel	11KV	II	02.40	04.05	01.25	All Indication	DTR fault at Tourist Hotel	-
3		Chilkaiguda	Golconda X Road	11KV	II	15.15	16.40	01.25	EL	Tree branches fallen on lines at Govt. School	-
4		Hussain Sagar	Lakdikapool	11KV	I	21.55	23.10	01.15	EL,OL	No Visible Fault	Arranged B/F on 11KV Meere Theatre fdr