

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		3		3		3			
6	RR(N)	54	550		13		13		13			
7	RR(E)	168	403		10		10		10			
8	Hyd	194	1044		31		31		31			
	Total	606	3055	0	57	0	57	0	57	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2	4	1	4	1	4			1 No. 33KV Still
2	NLG	144	988	2	26	2	26	2	26			
3	MDK	107	933	2	5	2	5	2	5			
4	SDPT			3	12	2	11	2	11			1 No. 33KV & 1 No. 11KV Still
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	9	47	7	46	7	46	0	0	
	Grand Total	1082	6468	9	104	7	103	7	103	0	0	

TSSPDCL - LMRC / Corporate office

Date: 02.08.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Nagarkurnool	Nagarkurnool	33KV	Nagarkurnool	13.54	14.15	00.21	E/L	No Visible Fault Due to Rain	Nagarkurnool	Alternate Supply Arranged From 33KV Ithole at 14:15Hrs
2		Balanagar	Chinchode	33KV	Shadnagar	21.10			E/L	Not Rectified	Chinchode	NO
1	NLG	Thungathurthi	Reddygudam	33KV	Suryapet	06.50	11.35	04.45	EL	Jumper Cut	Reddygudam	-
2		Suryapet	Chandupatla	33KV	Huzurnagar	01.55	10.35	08.40	EL	Due to tree branch fall on 33kv line	Chandupatla	-
1	MDK	Pashamailaram	SOL	33KV	Patancheru	12.33	16.10	03.37		BD due to Tree fallen line	SOL	-
2		Bollaram	Coca Cola	33KV	Patancheru	06.30	15.55	09.25		BD due to Jumper cut & Tree cutting	Coca Cola	-
1	SDP	Siddipet	Peddakodur	33KV	Siddipet	10.30				Breaker Failure	Peddakodur	-
2		Gajwel	Pregnapur	33KV	Gajwel	04.45	09.30	04.45		End kit failed	Pregnapur	-
3		Thunkibollaram	Seetharampally	33KV	Gajwel	20.17	21.15	00.58		OL&EL	Seetharampally	-

TSSPDCL - LMRC / Corporate office

Date: 02.08.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Nawabpet	Kondapur	11KV	Jadcherla	08.00	11.00	03.00		11KV Wire cut Near Kondapur (V)	-
2		Velgomla	Ayyavaripally	11KV	Jadcherla	11.20	14.30	03.10		11KV Wire cut Near Ayyavaripally (V)	-
3		Kandoor	Choudaipally	11KV	Jadcherla	04.20	09.10	04.50		11KV Insulator Failed Near Sunkavarampally (V)	-
4		Boothpur	Bhoothpur Town	11KV	Jadcherla	09.00	12.15	03.15		11KV Jumper cut Near Kotha Molgara side	-
1	NLG	Eduloor	Gadibaigudem	11KV	Nalgonda	10.10	13.30	03.20	E/L	11KV Jumper cut at SS-3	-
2		Pamanagundla	Yerasanigudem (1-Ph)	11KV	Nalgonda	14.40	16.05	01.25	E/L	11KV Jumper cut	-
3		Ch.Annaram	Vallala	11KV	Nalgonda	12.10	16.40	04.30	E/L	11KV Insulator failed	-
4		Gundrampally	Gundrampally	11KV	Nalgonda	14.37	17.08	02.31	E/L	AB switch post insulators failed at Sunkenapally(V)	-
5		Aregudem	Aregudem	11KV	Nalgonda	12.20	15.50	03.30	E/L	11KV jumper cut	-
6		Buggabaigudem	Abangapuram	11KV	Miryalaguda	05.00	07.30	02.30	E/L	insulator failed	-
7		Neelaigudem	Gantarao camp	11KV	Miryalaguda	08.00	09.21	01.21	E/L	jumper cut	-
8		Seethya thanda	Thopucherla 2	11KV	Miryalaguda	14.10	14.37	00.27	E/L	Conductor Snapped	-
9		Nuthankal	Polumalla	11KV	Suryapet	05.10	07.15	02.05	E/L	Line Snapped	-
10		Cheedella	Mukundapuram	11KV	Suryapet	05.45	07.30	01.45	E/L	Insulator flashover	-
11		Dirsincherla	Chillepally	11KV	Huzurnagar	12.15	15.30	03.15	EL	Due to Insulator failure	-
12		Mellacheruvu	Y madaram	11KV	Huzurnagar	01.07	04.00	02.53	EL	Due to 11Kv line cutted	-
13		Siripuram	Siripuram	11KV	Huzurnagar	04.00	07.00	03.00	EL	Due to 11Kv line snapped	-
14		Timmareddy gudem	Ganapavaram	11KV	Huzurnagar	04.00	07.00	03.00	EL	Due to Insulator failure	-
15		Anantharam	Hanmapuram	11KV	Bhongir	01.00	05.50	04.50	EL/OL	11 kv Disc Failed Near Hanmapuram Village	-
16		Bollepally	Surepally	11KV	Bhongir	11.00	14.00	03.00	EL/OL	11kv Disc Failed near Surepally Village	-
17		Golankonda	Golankonda	11KV	Bhongir	11.20	13.00	01.40	EL/OL	11kv Disc Failed near Golankonda Village	-
18		Datherpally	Mallapuram	11KV	Bhongir	05.00	11.20	06.20	EL/OL	11kv Line snapped near Mallapuram Village	-
19		Addagudur	CH.Ramaram	11KV	Bhongir	06.00	10.00	04.00	EL/OL	11KV Insulator Failed near Ch .Ramaram Village	-
20		Motakondur	Motakondur town	11KV	Bhongir	09.10	09.50	00.40	EL/OL	11 kv Pin Insulator Failed Near Motakondur Town	-
21		Ambala	Ambala	11KV	Bhongir	06.25	10.30	04.05	EL/OL	SS-9 11KV Insulator Failed 3 Phase B/d Single Phase Ok	-
22		Choutuppal	Lingijigudem	11KV	Choutuppal	08.00	10.00	02.00	EL/OL	11kv Line snapped near Sub_Station Choutuppal	-
23		Koyyalagudem	Dothigudem Indl	11KV	Choutuppal	11.05	12.25	01.20	EL/OL	11kv Disc Failed near Koyyalagudem Village	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
24		Mandollagudem	Nelapatla	11KV	Choutuppal	11.00	13.50	02.50	EL/OL	11KV Insulator Failed near Nelapatla Village	-
25		Juloor	Pilaipally	11KV	Choutuppal	06.00	10.00	04.00	EL/OL	11kv Line snapped near Pilaipally Village 3 Phase B/d Single Phase Ok	-
26		Juloor	Kapraipally	11KV	Choutuppal	06.00	09.00	03.00	EL/OL	11kv Insulator Failed near Kapraipally Village 3 Phase B/d Single Phase Ok	-
1	MDK	Pati	Shalimar	11KV	Patancheru	01.50	08.30	06.40		BD due to Insulator failed	-
2		Patancheru Town	MIA-I	11KV	Patancheru	04.52	05.52	01.00		BD due to Jumper cut	-
3		Gummadidala	Agrobell	11KV	Patancheru	01.35	09.35	08.00		BD due to Insulator failed	-
4		Kistareddypet	Industrial	11KV	Patancheru	18.45	20.45	02.00		BD due to Insulator failed	-
5		Hathnoora	Town Ind	11KV	Jogipet	02.00	04.00	02.00		BD due to 11KV Jumper cut	-
1	SDP	Pandilla	Pandilla Rural	11KV	Husnabad	00.00	07.40	07.40		BREAK DOWN	-
2		Potharam	Potharam Rural	11KV	Husnabad	01.10	07.20	06.10		INSULATOR FAIL	-
3		Katkur	Katkur Rural	11KV	Husnabad	07.00	09.15	02.15		INSULATOR FAIL	-
4		Akkannapet	Pakilnayak Thanda	11KV	Husnabad	15.35				BREAK DOWN	-
5		Gandipally	Nandaram	11KV	Husnabad	06.20	08.20	02.00		Jumper open	-
6		Gouravelly	Gudatipally	11KV	Husnabad	00.00	10.05	10.05		11KV pole Damage	-
7		Koheda	Venkateshwarapally	11KV	Husnabad	06.10	09.05	02.55		INSULATOR FAIL	-
8		Koheda	Kurella	11KV	Husnabad	06.40	09.20	02.40		INSULATORS FAIL	-
9		Koheda	Sriramulapally	11KV	Husnabad	06.00	11.45	05.45		Cross arm fail,Insulator fail	-
10		Gurjakunta	Gurjakunta 24 Hrs	11KV	Husnabad	00.00	09.00	09.00		INSULATOR FAIL	-
11		Guruvannapet	Guruvannapet	11KV	Husnabad	06.30	08.30	02.00		JUMPER OPEN	-
12		Nagapuri	Nagapuri	11KV	Husnabad	03.30	07.00	03.30		Disk Fail	-
1	RR S	Madinaguda	Hafeezpet	11KV	GCB	12.45	17.26	04.41		Tree fallen on the 11kv line at Hunman temple,Madinaguda (B/F from Chandanagar)	-
2		IJM	9th Phase	11KV	Kondapur	04.28	06.02	01.34		11kv Polymar insulator failed at HIG-65 9th Phase	-
3		KPHB	JNTU	11KV	Kondapur	05.53	08.00	02.07		11kv Polymar insulator damaged at Srindi tower and Polymar Disc failed at KPHB	-
1		Kompally	Garden Society	11KV	Medchal	15.23	15.58	00.35	BD	315KVA T/F 11KV Pin Insulator failed at High Vision	-
2		Kompally	Kompally	11KV	Medchal	17.55	18.59	01.04	BD	11KV Line AB Switch Opened at Dulapally X Road	-
3		Hudatruckpark	Sri Sai Nagar	11KV	Kukatpally	19.46	21.20	01.34	BD	11kv line AB Cable Failure at Sai Baba Nagar	-
4		Mayurinagar	Ramnareshnagar	11KV	Kukatpally	17.13	18.30	01.17	BD	11kv line PinInsulater failure at Rajadhani School	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
5	RR N	Athiwelly	Somaram	11KV	Medchal	04.30	07.20	02.50	BD	2No 11KV Pin Insulator Failed at Mahender Thota,Somaram	-
6		Ravalkole	Cheruvukatta	11KV	Medchal	06.00	10.50	04.50	BD	Tree Fallen on 11KV Line at Madhu farm(1 Pole Bend & 1 Pole damaged)	-
7		Kolthur	Mallannakatta	11KV	Medchal	15.40	18.00	02.20	BD	11KV Jumper cut and 2No Pin Insulators Failed at Pathakota Bavi,Kolthur	-
8		Bommarajpet	Karkalamma	11KV	Medchal	17.10	19.30	02.20	BD	11KV Conductor Snapped at CLR Poultry Farm,Bommarajpet	-
9		Athiwelly	Dabeerpur	11KV	Medchal	18.50	20.10	01.20	BD	Tree Fallen on 11KV Line at Dabeerpur Cheruvu	-
10		Jeedimetla-II	Apuroopa Colony	11KV	Jeedimetla	06.00	07.10	01.10	BD	11kv line AB Cable Failure Near Syaman Lab & B/F Komaply Phorma	-
11		Jeedimetla-II	NRSA	11KV	Jeedimetla	19.05	20.25	01.20	BD	11kv line AB Cable Endkit failure opp:Dhanalaxmi Polymares at Phase-IV	-
12		Aleap	RGK	11KV	Jeedimetla	03.20	05.20	02.00	BD	11kv PinInsulater failure at RGK	-
13		Gagillapur	chaithanya	11KV	Jeedimetla	12.10	13.40	01.30	BD	11kv PinInsulater failure at Gagillapur Village	-
1		RR E	Uppal	Raghavendra Colony	11KV	Habsiguda	10.40	11.10	00.30		11KV Pin Insulator failed near Marvadi T/F at Dharmapuri Colony
2	Uppal		Uppal	11KV	Habsiguda	12.10	13.15	01.05		11KV Pin Insulator failed near Sub Registrar Office at Laxma Reddy Colony	-
3	IDA Uppal		Devender Nagar	11KV	Habsiguda	22.30	23.12	00.42		11KV CT Failed at SS Yard & B/F supply taken from 11KV Srikrishna feeder	-
4	Cherlapally-II		Gajanana Thamara	11KV	Sainikpuri	10.40	12.58	02.18		11Kv Pin Insuletor fail at Phase-V (LM Rambabu)	-
5	Cherlapally-IV		RGK	11KV	Sainikpuri	22.45	23.45	01.00		11KV Pin Insulator Failed at Hanuman Temple Chinna Cherlapally	-
6	Keesara		Bogaram	11KV	Keesara	10.35	11.55	01.20		11KV 2Nos Pole damaged near Keesara Gutta Backside	-
7	Singapur		RGK	11KV	Keesara	13.30	14.30	01.00		11KV Pin Insulator failed at Power Grid Backside	-
8	P&T Colony		Medipally	11KV	Keesara	17.35	18.30	00.55		11KV Disc failed at Karthikeya Nagar	-
9	Chakripuram		S V Nagar	11KV	Keesara	17.50	19.20	01.30		11KV Disc failed at Madhura Nagar Colony	-
10	Chakripuram		Ayyappa	11KV	Keesara	18.40	20.20	01.40		11KV Post of insulator failed near Sheshank Enclave	-
1		Yellareddyguda	Savera	11KV	X	00.05	01.25	01.20	EL	UG Cable failed at Pakala Hotel	-----
2		H.M.T	Sri Sai Colony	11KV	VI	11.45	14.55	03.10	EL,OL-Rph	Pin Insulator flash over at Chinthal	-----
3		Gunrock	Subash Nagar	11KV	C-VI	12.15	13.45	01.30	EL,OL-Rph	DTR fault at Pump House	-----

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged	
4	HYD N	Clock Tower	Station Road	11KV	V	12.56	14.29	01.33	All Indication	Cable fault	Arranged B/F on 11KV Rly. Reservation fdr	
5		Pragatools	Indo Swing	11KV	VI	14.04	15.20	01.16	EL,OL-R&Bph	PKL Industries HT Service 3No. HG fuse burntout	Arranged B/F on 11KV Giri Nagar feeder	
6		Muffakamza College	Nandi Nagar	11KV	X	14.19	16.03	01.44	EL,OL-Yph	Tree branches fallen on lines & Disc Insulator flash over at Road No.14	At 15:26 Hrs Partial fdr arranged B/F on 11KV Road No.14 feeder	
7		Macha Bollarum	Chinthal Bazar	11KV	C-VI	14.32	15.48	01.16	EL,OL-Rph	Pin Insulator flash over at A.R.K Homes	-----	
8		Patigadda	Gas Mandi	11KV	V	18.32	20.00	01.28	EL,OL-Bph	No Visible Fault due to rain	Arranged B/F on 11KV R.P Road feeder	
9		I.I.C.T.	Deccan	11KV	V	19.22	21.30	02.08	EL	CT PT failed at Big Bazar	-----	
10		Addagutta	Ambedkar Nagar	11KV	C-VI	21.22	22.50	01.28	EL,OL-R&Yph	Big tree fallen on lines at Teachers Colony	-----	
11		Muffakamza College	Nandi Nagar	11KV	X	22.19	23.29	01.10	EL,OL	Faulty DTR at BSNL Office	-----	
12		Clock Tower	Natraj	11KV	V	21.15	23.45	02.30	All Indication	RMU End Kit failed at Kamath Hotel	Arranged B/F on 11KV S.P.Road fdr	
13		Macha Bollarum	Father Balaiah Nagar	11KV	C-VI	22.03	23.10	01.07	EL,OL	Tree branches fallen on lines at Bhavani Nagar	-----	
14		Marredpally	Nehru Nagar	11KV	C-VI	21.40	23.45	02.05	EL,OL-Bph	Disc Insulator flash over at Kasthuriba College	-----	
15		I.I.C.T.	Dal Mill	11KV	V	23.15	00.30	01.15	EL,OL	Pin Insulator flash over at Good Mate Apts	-----	
16		Clock Tower	Anjali	11KV	V	20.15	00.45	04.30	All Indication	Faulty 3No. HT services & 1No. Domestic (4No. DTR's kept off)	Arranged on 11KV Minerva fdr	
17		Tirumalagiri	Satya Sai Enclave	11KV	VI	22.46	01.07	02.21	EL,OL-Bph	Faulty mobile DTR at Road No.7	Partial fdr charged at 23:56Hrs (10/30Amp))	
1		HYD S	Falaknuma	Guntal Shah Darga	11KV	III	09.45	11.10	01.25	EL	2No. Conductors snapped at G.S.Darga	-
2			Devi Bagh	Shivalayam	11KV	III	21.40	23.04	01.24	EL	2No. Disc Insulators flash over at Anjali Complex	-
3			Teegalaguda	Housing Board Colony	11KV	VIII	21.40	23.36	01.56	All Indication	Line snapped at Mallikarjuna Temple	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
4		Miralam	Teegala Kunta	11KV	III	23.35	00.50	01.15	EL,OL	Tree branches fallen on lines at Naffa Function Hall	-
1	HYD C	Bathkammakunta	D.D.Colony	11KV	II	05.00	06.25	01.25	EL	Bird fallen on lines at Lezand Apts	-
2		Indira Park	Vivek Nagar	11KV	I	12.10	16.55	04.45	EL,OL-Rph	R.M.U Cable fault & Tree branches fallen on lines at Ashok Nagar	-
3		Bathkammakunta	Saibaba Temple	11KV	II	14.30	16.22	01.52	EL	Pin Insulator flash over at Vijaya Durga Residency	-
4		Bathkammakunta	D.D.Colony	11KV	II	14.34	16.15	01.41	EL	Pin Insulator flash over at Royal Habitate Apts	-
5		Indira Park	Secretariate	11KV	I	17.05	18.50	01.45	EL	No Visible Fault due to rain	-
6		Indira Park	Vivek Nagar	11KV	I	17.10	18.20	01.10	EL,OL-Bph	Cable fault in 3Way R.M.U at Ashok Nagar Nala	-
7		Lake View	Katriya Hotel	11KV	I	17.10	19.15	02.05	OL-Rph	HT Jumper cut & Tree branches fallen on lines at Katriya Hotel	-
8		Vittalwadi	Commssioner Office	11KV	I	17.22	19.02	01.40	EL,OL-Bph	Tree branches fallen on lines at HDFC Bank	-
9		Lake View	Katriya Hotel	11KV	I	19.58	21.35	01.37	EL,OL	Cable fault at Jaffer Ali Bagh	-
10		Jawahar Nagar	Ashok Nagar	11KV	I	20.57	22.40	01.43	OL-R&Bph	Tree branches fallen on lines at Ashok Nagar	-