

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	2	22	2	22	2	22			
7	RR(E)	168	403		10		10		10			
8	Hyd	194	1044		12		12		12			
	Total	606	3055	2	44	2	44	2	44	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		3		3		3			
2	NLG	144	988	1	25	1	25	1	25			
3	MDK	107	933		2		2		2			
4	SDPT				7		7		7			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	37	1	37	1	37	0	0	
	Grand Total	1082	6468	3	81	3	81	3	81	0	0	

TSSPDCL - LMRC / Corporate office

Date: 03.08.19

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Nalgonda	Indoor	33KV	Nalgonda	6:45	10:17	03.32	E/L	33KV Cable kits failed	Indoor	Alternate Supply Taken from 33 KV Rayanguda feeder at 10:17 AM
1	RR N	132KV Medchal	Athiwelly	33KV	Medchal	12:40	13:20	00.40		33KV GP Pally-I Jumper fallen on the 33KV Athiwelly Line	Athiwelly	No
2		132KV Medchal	Aliabad	33KV	Medchal	12.40	17.22	04.42		33KV Bus Bar Jumper cut in SS	Aliabad	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR N	Vijayanagar	Aruna Socity	11KV	Kukatpally	5:05	6:40	1:35	EL/OL	11kv Line disc failure at Laxminilayam,Arunasocity	No
2		Vikas	Co-ca-cola	11KV	Kukatpally	04.50	05.50	01.00	EL	11kv Line disc failure at Co-ca-cola X Road	No
3		Nizampet	Srinivasa Colony	11KV	Kukatpally	01.15	03.35	02.20	EL	11kv Line disc failure Near Road:2,at KTR Colony	No
4		JTPL	RTC Colony	11KV	Kukatpally	06.35	07.50	01.15	EL/OL	Tree branchesh fallen the 11kv line at Road:10, RTC Colony	No
5		Bachupally	Sai Nagar	11KV	Kukatpally	00.05	01.10	01.05	EL	Tree branchesh fallen the 11kv line at VNR Collage	No
6		Bachupally	SMS	11KV	Kukatpally	01.05	02.25	01.20	EL/OL	RMC Redmix Coampny CTPT Problem & Endkit falure at Bollaram X Raod	No
7		Jeedimetla-I	APIIC colony	11KV	Jeedimetla	12.40	14.00	01.20	EL/OL	Post of Insulater failure at APIIC colony	No
8		Suraram	Rajiv Gandhinagar	11KV	Jeedimetla	06.40	07.50	01.10	OL	11kv Line pin Insulater failure at Rajiv gandhinagar	No
9		Jeedimetla-III	Ramreddy Nagar	11KV	Jeedimetla	13.40	15.10	01.30	EL/OL	11kv Line Endkit failure at Ramreddynagar	No
10		Jeedimetla-IV	Axies	11KV	Jeedimetla	08.40	14.50	06.10	EL/OL	CTPT Failure near Kranthi Plastic,& Jumper cut at SS Yard	No
11		Bowrampet	Junnrum	11KV	Jeedimetla	01.30	04.15	02.45	EL	11kv Line Disk failure at opp:Hamar Dhaba	No
12		Petbasheerabad	Balaji Hospital	11KV	Medchal	08.50	10.20	01.30		11KV Jumper cut and replaced at Balaji Hospital	No
13		Petbasheerabad	Satyam Enclave	11KV	Medchal	09.45	10.40	00.55		Tree fallen on the 11KV Line at Satya Enclave	No
14		Subhash Nagar	Meenakshi	11KV	Medchal	11.25	12.20	00.55		No visible fault	No
15		UMCC	Crusher	11KV	Medchal	11.35	12.30	00.55		11KV Brass patti cut and repalced at Kaiser Nagar	No
16		Subhash Nagar	Meenakshi	11KV	Medchal	13.15	14.50	01.35		11KV Line AB Switch opened at SN Reddy Enclve (Tree Fallon on the 11KV Line)	No
17		Athiwelly	Padmaja	11KV	Medchal	10.30	13.10	02.40		Tree fallen on the 11KV Line Majeed Athiwelly	No
18		Ravalkole	IDA Ganapathi	11KV	Medchal	06.30	08.58	02.28		11KV Disc failed at Mercury Company	No
19		Town Medchal	Country Club	11KV	Medchal	05.05	06.15	01.10		11KV Pin insulator failed at Govt Hospital	No
20		ICICI	Adama	11KV	Medchal	00.00	08.00	08.00		11KV Pin insulator failed at Larus Lab opp	No
21		Ravalkole	IDA Ganapathi	11KV	Medchal	12.18	14.20	02.02		11KV Pin Insulator failed at Archana Foultry form	No
22		Medchal	IDA Kandlakoya	11KV	Medchal	14.40	19.05	04.25		2 Poles & 100KVA DTR Damaged at Shekthi Rabar company (100KVA DTR Jumper opened)	No